MACADAM








FORD Tourneo Courier: 8635-MRP

Vinnumber:	**WF01NBER71RR11543**	Versionname:	**1.0 Ecoboost 92kW (125CV) Trend monovolumen compacto 92kW 5P manual**
First Registrationdate:	**27/05/2024**	Fiscalpower:	
Expertise Mileage:	**111400**	Power Kw:	
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Steel**
Transmission:			
Fueltype:	**Petrol**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Light Commercial Vehicle**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**1**	Central consol F	
Number keys remote	**1**	Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**195/65/15/91 V**			
	Fr.L.	**Other: 8 mm**	Fr.R.	**Other: 5 mm**
	Re.L.	**Other: 5 mm**	Re.R.	**Other: 5 mm**

Tyre profile depth FL	**8.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**195/65 R 15 91 V**
Tyre size FR	**195/65 R 15 91 V**
Tyre size RL	**195/65 R 15 91 V**
Tyre size RR	**195/65 R 15 91 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**263**
Tyre make FR	**263**
Tyre make RL	**263**
Tyre make RR	**263**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Interior, Dirty, Cleaning








Boot lid covering R, Scratch(es), Replace




User's manual, Missing, Repair/replace (lump sum)




Registration document, Missing, Repair/replace (lump sum)




Ignition key, Missing, Repair/replace (lump sum)




Roof liner, Scratch(es), Replace




Floor covering FL, Burned, Replace




Rear light L, Crack, Replace




Wing RL, Scratch(es), Paint




Wing FL, Scratch(es), Paint




Wing FL, Scratch(es), Paint




Bumper F, Scratch(es), Paint





Windscreen, Stone chip(s), Forfeit




Outside rear-view mirror housing R, Scratch(es), Acceptable




Wing RR, Dent(s), Repair and paint (complete)




Sliding door R, Scratch(es), Paint




Bumper R, Scratch(es), Paint





Tailgate / Boot, Scratch(es), Paint




Tyres, No damage, Check











ALPHABET

Datos del vehículo

Marca	FORD	Matrícula	8635-MRP
Modelo	Tourneo Courier	VIN	WF01NBER71RR11543
Versión	1.0 Ecoboost 92kW (125CV) Trend monovolumen compacto 92kW 5P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
20/08/2024	Sustitución	13315	CASADO MUÑIZ, JOSE MANUEL
02/12/2024	Revisión 1 año	25014	MARTOS TOBALO S.A.

Fecha	Descripción	Kilómetros	Taller