



DS 7 CROSSBACK: GA-108-TZ

Vinnumber:	VR1J45GFUMY519675	Versionname:	DS DS 7 CROSSBACK PureTech 180 Automatique RIVOLI VP [5P] bva 8-180CH-10cv (SUV)
First Registrationdate:	19/07/2021	Fiscalpower:	
Expertise Mileage:	90509	Power Kw:	132
Bodytype:	SUV	Body colour:	Dark Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Seats electric F R	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Headlights Xenon/LED/Laser	
Steering wheel multifunctional		Front parking sensors	
Steering wheel leather		Rear parking sensors	
Seats F heated		Rear view camera	
Type of climate control	Autom climate control	Seat cover lining	Lining Leather

Tyres

	235/50/19/99 H			
Summer tyres:	Fr.L.	Bridgestone: 30%	Fr.R.	Bridgestone: 35%
	Re.L.	Bridgestone: 0%	Re.R.	Bridgestone: 10%
Tyre profile depth FL				6.1
Tyre profile depth FR				5.8
Tyre profile depth RL				8.0
Tyre profile depth RR				7.6
Tyre size FL				235/50 R 19 99 H
Tyre size FR				235/50 R 19 99 H
Tyre size RL				235/50 R 19 99 H
Tyre size RR				235/50 R 19 99 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)





Alloy rim FL bitone/polychrome, Scratch(es), Acceptable



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing RL, Scratch(es), Paint



Door FL, Scratch(es), Paint



Bumper grille, Unclassped, Dismount/Mount



Door FR, Scratch(es), Acceptable



Historique Maintenance

Immatriculation: GA-108-TZ Date de 1ère immatriculation: 19/07/2021

Modèle: DS 7 CROSSBACK PureTech 180 Automatique RIVOLI VP [5P] bva 8-180CH-10cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
02/02/2026	84.122	STELLANTIS &YOU FRANCE SAS	DIVERS CLIM
	0		REVISION
	0		ECLAIRAGE DE PLAQUE RPLT
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
24/06/2025	62.237	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
24/01/2025	54.392	TRUJAS SAS	FILTRE CLIM RPLT
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		DIVERS ELEC
	0		DIVERS
	0		REVISION
	0		BOITIER D ALLUMAGE RPLT
	0		FILTRE A AIR RPLT
10/12/2024	52.892	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		REMPLACEMENT PNEUS HIVER
30/11/2023	35.456	TRUJAS SAS	REVISION
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
22/11/2022	18.184	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE
28/10/2022	16.815	STELLANTIS &YOU FRANCE SAS	REVISION