

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia											
				Policyholder				Opposite party				Opposite party company									
				Operation 2026		Claim number			Code / Agency				Date accident 03/07/2026								
				Expert code		Adjuster code			Policy number			Injured person can recover the VAT									
Date assignment 03/07/2026		Date first survey 13/07/2026		Place SAN GIULIANO MILANESE		C/O VAR		Repairs TO START		Photo		Lien in favor of		Expiry date							
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)														Formerly plate							
Lessee / Co-owner														Date of overhaul							
Vehicle (Brand - Model - Version) HYUNDAI TUCSON 1.6 HEV 2wd 230cv Xline Auto								Plate GP748FV		Vin Chassis TMAJD811BPJ191399				First Registration 31/05/2023							
Usage status NON CONOSCIUTO		Km 75052		Tyres % 60		Color GRIGIO		Type of enamel METALLIZED/DOUBLE				Consistency of damage		Type of Expert's report NOT DEFINITIVE							
Equipment																					
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0										Wheelbase		Seats No. 0		Axles 0	
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses															
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts * (VAT excluded)			
								Dif		Time		Dif		Time		Dif		Time			
1 86612N7000 Rear bumper lower part								S				S				S					
1 86670N7060 Rear bumper lower cladding								S				S				S					
1 92403N7120 Rear internal part headlamp								S				S				S					
1 67111N7000 Roof								G				G				G					
1 66400N7000 Front bonnet								M				M				M					
1 71110N7A00 Compartment structure of front door L								M				M				M					
1 71120N7A00 Compartment structure of front door R								M				M				M					
1 86656N7000 Rear bumper upper part L								M				M				M					
1 76004N7005 Front door R								M				L				M					
1 86511N7000 Front bumper upper part								M				M				M					
1 76003N7005 Front door L								L				L				L					
1 77003N7010 Rear door L								L				L				L					
1 72800N7010 Rear hatch L								L				L				L					
1 Codice Ricambio Cerchio ant. - PRM R																					
1 Codice Ricambio Sedile ant. - PRM L																					

New for old value (N)	Remarks Pneum. 215/65 R17 - ant. Michelin, post. Good Year. Vhl grandinato.
-----------------------	---

ALPHABET

Telaio TMAJD811BPJ191399

GP748FV

HYUNDAI TUCSON 1.6 HEV 2wd 230cv Xline Auto sports utility vehicle 230CV 5P automatico

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
37.831	23/12/24	Tagliando a 30 000 km	Tagliando a 30 000 km
50.153	26/06/25	Tagliando a 50 000 km	***Service at 50 000 km