



Volkswagen T-Roc.: P811FP

| | | | |
|-------------------------|-------------------------|-------------------------|---|
| Vinnnumber: | WVGZZA1ZNV087587 | Versionname: | T-Roc 1.5 TSI 110kW Sport Business R DSG |
| First Registrationdate: | 3/03/2022 | Fiscalpower: | |
| Expertise Mileage: | 153810 | Power Kw: | 110 |
| Bodytype: | | Body colour: | Deep Black Pearl metallic |
| Gearbox: | Automatic | Paint type: | Metallic |
| Transmission: | | Type of rims (mounted): | Aluminium |
| Fueltype: | Petrol | Parking lot: | 557 |
| Number of seats: | 5 | | |
| Type of rims (mounted): | Aluminium | | |
| Maintenance needed: | No | | |

Options

| | | |
|-----------------------|----------|----------------------|
| Number of keys total | 2 | Lining semi-leather |
| GPS | | Rear parking sensors |
| Autom climate control | | |
| Radio multimedia | | |

Tyres

| Location | Position | Measures | Depth | Make | Type |
|----------|----------|------------------------------------|--------|-------------|--------|
| Front | Left | 215 / 50 / 18 / 92 / W / Aluminium | 2,3 mm | Bridgestone | Summer |
| | Right | 215 / 50 / 18 / 92 / W / Aluminium | 2,5 mm | Bridgestone | Summer |
| Rear | Left | 215 / 50 / 18 / 92 / W / Aluminium | 2,0 mm | Bridgestone | Summer |
| | Right | 215 / 50 / 18 / 92 / W / Aluminium | 1,3 mm | Bridgestone | Summer |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (rapid charge) | 0 |
|--|----------|

Seat cover R, Stain, Cleaning



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Tyre RR, Worn, Replace



Wing RR, Chemical polution, Polish



Outer door handle FR, Scratch(es), Repair and paint (complete)



Rear window, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



| | |
|-----------------------|---|
| Kenteken | P811FP |
| Merk Model | Volkswagen T-Roc 1.5 TSI 110kW Sport Business R DSG |
| Brandstofsoort | Benzine |
| Datum deel1 | 03-03-22 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|-----------------|----------------|---------------------------------|
| 19-12-25 | 138.047 | APK |
| 19-12-25 | 138.047 | Onderhoudsbeurt |
| 19-12-25 | 138.047 | Remblokken achterzijde |
| 19-12-25 | 138.047 | Remvloeistof |
| 19-12-25 | 138.047 | Ruitenwischerblad(en) voorzijde |
| 19-12-25 | 138.047 | Sleutelbatterij |
| 06-11-24 | 95.260 | Vervanging band |
| 07-06-24 | 79.932 | Reparatie band(en) |
| 31-05-24 | 79.291 | Onderhoudsbeurt |
| 31-05-24 | 79.291 | Vervanging band |
| 18-01-23 | 31.643 | Onderhoudsbeurt |