



BMW 3 Reeks (KKL): 2BPL858

Vinnumber:	WBA6N91050FM41857	Versionname:	320e Touring (G21) 2.0i 204pk/cv 4p
First Registrationdate:	4/02/2022	Fiscalpower:	
Expertise Mileage:	123134	Power Kw:	120
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	over 09/2027 of 12000km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/50/17/98 H			
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 2 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				2.0
Tyre size FL				225/50 R 17 98 H
Tyre size FR				225/50 R 17 98 H
Tyre size RL				225/50 R 17 98 H
Tyre size RR				225/50 R 17 98 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Alloy rim FL polished, Chemical polution, Acceptable



Charging cable (normal), Missing, Check



Boot carpet, Missing, Repair/replace (lump sum)



Bumper R, Dent(s), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Kenteken	2BPL858
Merk Model	BMW 320e Touring (G21) 2.0i 204pk/cv 4p
Brandstofsoort	Benzine
Datum deel1	2/4/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
9/24/25	101,623	BMW/MINI service standaard omvang	Uitvoeren
9/24/25	101,623	klein materiaal	
9/24/25	101,623	service microfilter	Uitvoeren
9/24/25	101,623	service motorolie	Uitvoeren
2/4/25	82,428	batterij	Vervangen
2/4/25	82,428	BMW/MINI service standaard omvang	Uitvoeren
2/4/25	82,428	remvloeistof	Vervangen
6/19/24	66,561	BMW/MINI service standaard omvang	Uitvoeren
6/19/24	66,561	BMW/MINI service voertuig-check	Uitvoeren
6/19/24	66,561	bougie	Vervangen
6/19/24	66,561	parkeersensor vooraan	Vervangen
6/19/24	66,561	ruitenswisserrubber achter	Vervangen
6/19/24	66,561	ruitenswisserrubber vooraan	Vervangen
6/19/24	66,561	service luchtfilter	Uitvoeren
6/19/24	66,561	service microfilter	Uitvoeren
6/19/24	66,561	service motorolie	Uitvoeren
5/12/23	33,993	BMW/MINI service standaard omvang	Uitvoeren
5/12/23	33,993	service microfilter	Uitvoeren
5/12/23	33,993	service motorolie	Uitvoeren