APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	HM Tongeren
Make:	MERCEDES
Model / version:	EQC
Wine:	W1K8P9AB8PF050144
Plate:	2CMH246
Mileage:	55385
SOH:	
First registration:	14/09/2022
Color:	BLUE CAVANSI

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book	
Number of keys:	2
Original key:	✓


PICTURES










































WINE INFORMATION

Radio	Adaptive headlights	Smart projectors
LED spotlights	Air Conditioning	Air conditioning refrigerant 1234YF
Metallic varnished	Hard varnish (to avoid displaying group 1700)	Electrically adjustable left-side mirror
Electrically adjustable right-side mirror	Automatic day/night left rearview mirror	Electrically folding mirrors
Left rearview mirror with GPS antenna	Left-hand rearview mirror with phone antenna	Automatic day/night interior rearview mirror
Heated front left seat	Heated front seats	Fabric trim
Front parking assistance	Rear parking assistance	Parking assistance
Front camera	Rearview camera	Cruise control
Displaying and reading road signs	Electrically operated trunk opening	Alarm
Emergency call	Acoustic front door windows	Electric sunroof

Glass sunroof	Passenger airbag can be deactivated	Lane Keeping Assistant
Autonomous emergency braking assistance (urban)	Forward collision warning	EQ Star
LTE communication module	chassis number F043153	année de modifications 2022 (modèle 2023)
Keyless-Go avec fonction Start	assistant d'angle mort	radio Digitale (DAB)
câble de charge pour Wallbox et bornes de recharge publiques IEC 62196	éclairage périphérique	encarts décoratifs look Matrix gris
avertissement sonore périphérique	indicateur de statut du port de ceinture aux places arrières	extincteur
contrôle de la pression des pneus	235/55 R 19 .. V	8 J X 19 ALU
TIREFIT avec compresseur de gonflage des pneus	chargeur Combo 2/Type 2	ceintures de sécurité ar avec limitateur d'effort et Softstop
ensemble de pays Euro NCAP	charge en AC avec capacité de 11 kW	protection compartiment chargement EASY-PACK

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		235/55R19 105W	Summer		?
Front right	5 mm		235/55R19 105W	Summer		?
Rear left	5 mm		235/55R19 105W	Summer		?
Rear right	5 mm		235/55R19 105W	Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Contact key - Boordcomputer resetten	Not original part
2	Windscreen	Crack
3	Door FL	Scratch(es)
4	Inner door sill RL	Dent(s)
5	Alloy rim RL polished	Grooved
6	Bumper trim R	Grooved
7	Inner door sill RR	Dent(s)

Total: 7

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
8	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Contact key - Boordcomputer resetten - Not original part




2 - Windscreen - Crack




3 - Door FL - Scratch(es)







4 - Inner door sill RL - Dent(s)







5 - Alloy rim RL polished - Grooved







6 - Bumper trim R - Grooved





7 - Inner door sill RR - Dent(s)




8 - Bodywork - Dent(s) and scratch(es) - Renta®












SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

17/09/2026 11:11

