



VOLVO V60:

| | | | |
|-------------------------------------|--------------------------|-------------------------|-----------------------|
| Vinnumber: | YV1FW7481J2404512 | Versionname: | D2 eco Kinetic |
| First Registrationdate: | 25/03/2019 | Fiscalpower: | |
| Expertise Mileage: | 142109 | Power Kw: | 88 |
| Bodytype: | | Body colour: | Grey |
| Gearbox: | MAN 6 VIT | Type of rims (mounted): | Aluminium |
| Transmission: | | Parking lot: | 2703 |
| Fueltype: | Diesel | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | Yes | | |
| Registration Certificate Home (BE): | No | | |

Options

| | | | |
|---------------------------------|------------------------------|-----------------------|-------------------|
| Number of keys total: | 2 | Luggage cover: | |
| Cruise Control: | | Rear parking sensors: | |
| Steering wheel multifunctional: | | Type of Tow bar: | No Tow bar |
| Radio multimedia: | | | |
| Type of headlighting: | Headlighting Halogen | | |
| Type of GPS: | GPS big screen color | | |
| Type of Lining: | Lining fabrics | | |
| Type of climate control: | Autom climate control | | |

Limited Technical Inspection

Tyres

| 205/60/16/96 W | | | | |
|-----------------------|-------|-----------------------|-------|-------------------------|
| Summer tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 3 mm | Re.R. | Michelin: 3 mm |
| Tyre profile depth FL | | | | 3.0 |
| Tyre profile depth FR | | | | 3.0 |
| Tyre profile depth RL | | | | 3.0 |
| Tyre profile depth RR | | | | 3.0 |
| Tyre size FL | | | | 205/60 R 16 96 W |
| Tyre size FR | | | | 205/60 R 16 96 H |
| Tyre size RL | | | | 205/60 R 16 96 W |
| Tyre size RR | | | | 205/60 R 16 96 H |
| Tyre type FL | | | | Summer |
| Tyre type FR | | | | Summer |
| Tyre type RL | | | | Summer |
| Tyre type RR | | | | Summer |
| Tyre make FL | | | | 261 |
| Tyre make FR | | | | 261 |
| Tyre make RL | | | | 261 |
| Tyre make RR | | | | 261 |

Assistance equipment

| | | | |
|---|------------|-------|------------|
| Emergency spare wheel: | Yes | Jack: | Yes |
| Number of charging cables (normal): | 0 | | |
| Number of charging cables (rapid charge): | 0 | | |

| | |
|----------------------------|----------------|
| Total cost ex VAT: | 3176,70 |
| Interior, Dirty, Cleaning: | 175,04 |



Bumper F, Scratch(es), Repair and paint (complete) 296,58



Bonnet, Dent(s), Repair and paint (complete) 406,19




Bonnet, Dent(s), Repair and paint (complete) 406,19



Windscreen, Repaired, Acceptable 0,00



Alloy rim FL, Scratch(es), Repair and paint (complete) 133,03



Door FL, Dent(s) and scratch(es), Replace and paint 0,00



A-pillar left, Dent(s), Spot repair 148,33



Door RL, Scratch(es), Repair and paint (complete) 445,79



Sill trim L, Scratch(es), Repair and paint (complete) 434,80



Alloy rim RL, Scratch(es), Repair and paint (complete) 133,03



Rubber seal for boot lid, Deformed / Strained, Replace 168,11



Bumper R, Scratch(es), Repair and paint (complete) 296,58



Rear window, Scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Acceptable 0,00



Tyre RR, Worn, Acceptable

0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable

0,00



Alloy rim FR, Scratch(es), Repair and paint (complete)

133,03



Wing RR, Repaired, Acceptable

0,00



Step R, Dent(s), Acceptable

0,00

