MACADAM








Volkswagen Polo (UKL): 2BWJ470

Vinnumber:	**WVWZZZAWZNU028395**	Versionname:	**Polo Life 1.0TSi 95pk/cv 5p**
First Registrationdate:	**19/04/2022**	Fiscalpower:	
Expertise Mileage:	**97014**	Power Kw:	**70**
Bodytype:		Type of rims (mounted)	**Steel**
Gearbox:	**MAN 5 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**+ 24200 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**185/65/15/92 V**			
	Fr.L.	**Uniroyal: 7 mm**	Fr.R.	**Uniroyal: 6 mm**
	Re.L.	**Michelin: 6 mm**	Re.R.	**Michelin: 5 mm**

Tyre profile depth FL	**7.0**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**185/65 R 15 92 V**
Tyre size FR	**185/65 R 15 92 V**
Tyre size RL	**185/65 R 15 92 V**
Tyre size RR	**185/65 R 15 92 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**265**
Tyre make FR	**265**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Bumper F, Bad repair, Repair and paint (complete)





Wheel cover RL, Scratch(es), Replace




Boot lid covering R, Scratch(es), Acceptable




Bumper R, Scratch(es), Repair and paint (complete)





Wheel cover FR, Scratch(es), Replace





Wing RR, Scratch(es), Repair and paint (complete)




Onderhoudshistorie van: WVWZZZAWZNU028395

ALPHABET

Kenteken	2BWJ470
Merk Model	Volkswagen Polo Life 1.0TSi 95pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	4/19/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
8/21/26	91,160	bandenherstelmiddel (garage)	
8/21/26	91,160	Inspectie met olieververvanging (vast in	Uitvoeren
8/21/26	91,160	klein materiaal	
8/21/26	91,160	koelwatervloeistof	Vervangen
8/21/26	91,160	luchtfilter	Vervangen
8/21/26	91,160	luchtfilter interieur	Vervangen
8/21/26	91,160	remschijven en blokken vooraan	Vervangen
8/21/26	91,160	ruitenwisserrubber achter	Vervangen
8/21/26	91,160	ruitenwisserrubber vooraan	Vervangen
8/21/26	91,160	ruitenwisservloeistof	Bijvullen/-laden
8/21/26	91,160	vacuumslang (inspuiting)	Uitvoeren
2/13/25	53,025	bougie	Vervangen
2/13/25	53,025	klein materiaal	
2/13/25	53,025	luchtfilter interieur	Vervangen
2/13/25	53,025	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
2/13/25	53,025	remvloeistof	Vervangen
2/13/25	53,025	ruitenwisserrubber achter	Vervangen
2/13/25	53,025	ruitenwisserrubber vooraan	Vervangen
3/23/23	28,248	Inspectie met olieververvanging (vast in	Uitvoeren
3/23/23	28,248	klein materiaal	Uitvoeren
3/23/23	28,248	ruitenwisservloeistof	Bijvullen/-laden
11/3/22	16,959	controle niveaus	Uitvoeren
11/3/22	16,959	klein materiaal	