MACADAM









KIA CEED SW: GL-530-QZ

Vinnumber:	**U5YH5812APL143575**	Versionname:	**KIA CEED SW 1.0 T-GDI 120 ISG ACTIVE BUSINESS SW VP [5P] bvm 6-120CH-6cv (break)**
First Registrationdate:	**16/01/2023**	Fiscalpower:	
Expertise Mileage:	**157728**	Power Kw:	**88**
Bodytype:	**Break**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Petrol**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	**HD**	Rear parking sensors	
Windows electric F		Rear view camera	
Windows electric R		Seat cover lining	**Lining Other**
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**205/55/16/91 V**			
	Fr.L.	**Other: 45%**	Fr.R.	**Other: 40%**
	Re.L.	**Hankook: 45%**	Re.R.	**Hankook: 45%**

Tyre profile depth FL	**5.4**
Tyre profile depth FR	**5.7**
Tyre profile depth RL	**5.4**
Tyre profile depth RR	**5.3**
Tyre size FL	**205/55 R 16 91 V**
Tyre size FR	**205/55 R 16 91 V**
Tyre size RL	**205/55 R 16 91 H**
Tyre size RR	**205/55 R 16 91 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**263**
Tyre make FR	**263**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Bumper F, Scratch(es), Paint







Side repeater R, Scratch(es), Replace




Wing FR, Dent(s), Repair and paint (complete)




Bumper R, Scratch(es), Paint












ALPHABET

Historique Maintenance

Immatriculation: **GL-530-QZ** Date de 1ère immatriculation: **16/01/2023**

Modèle: **Kia CEED SW 1.0 T-GDI 120 ISG ACTIVE BUSINESS SW VP [5P] bvm 6-120CH-6cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
22/06/2026	146.428	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
			PERMUTATIONS PNEUS
			PERMUTATIONS PNEUS
			PERMUTATIONS PNEUS
19/06/2026	146.198	ROURE AUTOMOBILES	BALAIS ESSUIE GLACE AV
			LAMPE RPLT
			DISQUES PLAQUETTES AV RPLT
			REVISION
09/02/2026	128.306	ROURE AUTOMOBILES	FILTRE A AIR RPLT
			REVISION ET CLIM
			BATTERIE RPLT
			LIQUIDE DE FREIN
18/12/2025	121.860	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
19/09/2025	110.265	ROURE AUTOMOBILES	REVISION
			REFUS
30/05/2025	97.291	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
23/05/2025	96.734	ROURE AUTOMOBILES	REVISION ET CLIM
			DISQUES PLAQUETTES AV RPLT
			LIQUIDE DE FREIN
			PLAQUETTES AR RPLT
09/01/2025	80.667	ROURE AUTOMOBILES	REVISION
			BALAIS ESSUIE GLACE AV AR
			BOITIER D ALLUMAGE RPLT
19/12/2024	76.834	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS HIVER
13/09/2024	65.153	ROURE AUTOMOBILES	LIQUIDE DE FREIN
			FILTRE A AIR RPLT
			REVISION ET CLIM
25/04/2024	49.125	ROURE AUTOMOBILES	DISQUES PLAQUETTES AV RPLT
			REVISION
08/12/2023	32.291	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS HIVER
06/12/2023	32.034	ROURE AUTOMOBILES	PLAQUETTES AV RPLT

Historique Maintenance

Immatriculation: **GL-530-QZ** Date de 1ère immatriculation: **16/01/2023**

Modèle: **Kia CEED SW 1.0 T-GDI 120 ISG ACTIVE BUSINESS SW VP [5P] bvm 6-120CH-6cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
			LIQUIDE DE FREIN
			REVISION ET CLIM
03/08/2023	15.774	ROURE AUTOMOBILES	REVISION