



BMW 2 Reeks Active Tourer (UKL): 2DSM941

Vinnumber:	WBA21BX0007M86238	Versionname:	218i Active Tourer (U06) 1.5i 136pk/cv 5p Aut.
First Registrationdate:	13/06/2023	Fiscalpower:	
Expertise Mileage:	22078	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	+ 16000 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/65/16/95 W				
Summer tyres:	Fr.L.	Nexen: 5 mm	Fr.R.	Nexen: 5 mm
	Re.L.	Nexen: 6 mm	Re.R.	Nexen: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				205/65 R 16 95 W
Tyre size FR				205/65 R 16 95 W
Tyre size RL				205/65 R 16 95 W
Tyre size RR				205/65 R 16 95 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				1957072
Tyre make FR				1957072
Tyre make RL				1957072
Tyre make RR				1957072

Assistance equipment

Bumper F, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Acceptable



Alloy rim RR, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable



Kenteken	2DSM941
Merk Model	BMW 218i Active Tourer (U06) 1.5i 136pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	6/13/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
3/18/26	21,521	BMW/MINI service standaard omvang	Uitvoeren
3/18/26	21,521	controle niveaus	Uitvoeren
3/18/26	21,521	remvloeistof	Vervangen
3/18/26	21,521	ruitenwisservloeistof	Bijvullen/-laden
10/16/25	20,478	controle niveaus	Uitvoeren
4/3/25	17,491	batterij	Vervangen
4/3/25	17,491	BMW/MINI service standaard omvang	Uitvoeren
4/3/25	17,491	klein materiaal	
4/3/25	17,491	service microfilter	Uitvoeren
4/3/25	17,491	service motorolie	Uitvoeren
11/28/24	15,073	controle niveaus	Uitvoeren
4/9/24	8,807	controle niveaus	Uitvoeren
4/9/24	8,807	klein materiaal	
4/9/24	8,807	ruitenwisserrubber vooraan	Vervangen