

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia									
				Policyholder				Opposite party				Opposite party company							
				Operation 2026		Claim number		Code / Agency				Date accident 16/07/2026							
				Expert code		Adjuster code		Policy number				Injured person can recover the VAT							
Date assignment 16/07/2026		Date first survey 20/07/2026		Place BRASIELLO SALOMONE		C/O RIP		Repairs TO START		Photo Lien in favor of									
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)										Formerly plate									
Lessee / Co-owner										Date of overhaul									
Vehicle (Brand - Model - Version) HYUNDAI TUCSON 1.6 T-GDI MHEV 2wd 150cv Excellence DCT								Plate GF860SD		Vin Chassis TMAJE81BGMJ015866									
Usage status NON CONOSCIUTO		Km 50448		Tyres % 60		Color GRIGIO		Type of enamel METALLIZED/DOUBLE		Consistency of damage Type of Expert's report NOT DEFINITIVE									
Equipment																			
Approval code		For commercial vehicles		Carrying Qls 0		Tare, Q 0						Wheelbase		Seats No. 0					
Axles 0		Commercial value (C)		Wrecked car value		Value by difference						Ancillary expenses							
Damaged items / restoration operations								SR		LA		VE		ME		D.M. S.C.		Costs of spare parts + (VAT excluded)	
								Dif		Time		Dif		Time		Dif		Time	
1 Codice Ricambio RIPRISTINO CERCHIO POST SX R 19																			
1 Codice Ricambio RIPRISTINO CERCHIO POST DX R 19																			
1 Codice Ricambio RIPRISTINO CERCHIO ANT DX R 19																			
1 66400N7000 Front bonnet								L				L				L			
1 67111N7000 Roof								M				M				M			
1 71120N7A00 Compartment structure of front door R								M				M				M			
1 86511N7000 Front bumper upper part								M				M				M			
1 86596N7010 Trim of front bumper R								L				L				L			
1 86670N7060 Rear bumper lower cladding								L				L				L			
1 77004N7000 Rear door R								L				L				L			
1 76004N7005 Front door R								L				L				L			
1 Codice Ricambio Smacchiatura interni																			

New for old value (N)	Remarks PNEUMATICI ESTV HANKOOK 235/50/R19 103 Y RILEVATI DANNI DA GRANDINE
-----------------------	---