MACADAM










## Renault Trafic: VND85L

| | | | |
|---|---|---|---|
| Vinnumber: | **VF1FL000768490169** | Versionname: | **Trafic T29 2.0 DCI Energy 88kW Comfort GB L1H1** |
| First Registrationdate: | **11/11/2021** | Fiscalpower: | |
| Expertise Mileage: | **140409** | Power Kw: | **88** |
| Bodytype: | | Body colour | **Blanc Glacier standaard** |
| Gearbox: | **MAN 6 VIT** | Paint type | **Opaque** |
| Transmission: | | Type of rims (mounted) | **Steel** |
| Fueltype: | **Diesel** | Parking lot | **894** |
| Number of seats | **3** | | |
| Type of rims (mounted) | **Steel** | | |
| Maintenance needed | **No** | | |

## Options

| | | | |
|---|---|---|---|
| Number of keys total | **3** | Rear parking sensors | |
| GPS | | Hook | |
| Manual climate control | | Sliding door right-side | |
| Radio multimedia | | Sliding door left-side | |

## Tyres

| Location | Position | Measures | Depth | Make | Type |
|---|---|---|---|---|---|
| Front | Left | 215 / 65 / 16 / 109 / T / Steel | 5,0 mm | Continental | All season |
| | Right | 215 / 65 / 16 / 109 / T / Steel | 4,3 mm | Continental | All season |
| Rear | Left | 215 / 65 / 16 / 109 / T / Steel | 7,2 mm | Continental | All season |
| | Right | 215 / 65 / 16 / 109 / T / Steel | 6,2 mm | Continental | All season |

## Assistance equipment

### Bumper F, Scratch(es), Smart repair






### Windscreen, Stone chip(s), Windscreen repair




### Bodywork, Chemical polution, Polish







# Onderhoudshistorie van: VF1FL000768490169

ALPHABET

| | |
|---|---|
| **Kenteken** | VND85L |
| **Merk Model** | Renault Trafic T29 2.0 DCI Energy 88kW Comfort GB L1H1 |
| **Brandstofsoort** | Diesel |
| **Datum deel1** | 11/11/21 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|---|---|---|
| 12/5/25 | 111,831 | APK |
| 12/5/25 | 111,831 | Fijnstofmeting |
| 12/5/25 | 111,831 | Onderhoudsbeurt |
| 12/20/24 | 82,045 | Vervanging band |
| 12/19/24 | 82,045 | APK |
| 12/19/24 | 82,045 | Brandstoffilter |
| 12/19/24 | 82,045 | Fijnstofmeting |
| 12/19/24 | 82,045 | Luchtfilter |
| 12/19/24 | 82,045 | Onderhoudsbeurt |
| 12/19/24 | 82,045 | Remvloeistof |
| 1/2/24 | 64,544 | Radiateur |
| 12/28/22 | 42,371 | Onderhoudsbeurt |