



CITROËN BERLINGO: FV-579-LW

Vinnumber:	VR7EFYHWCLJ778620	Versionname:	CITROËN BERLINGO Taille M 1000kg BlueHDi 75 S&S BVM Club VU [4P] bvm 5-75CH-5cv (fourgonnettesimple cabine)
First Registrationdate:	30/11/2020	Fiscalpower:	55
Expertise Mileage:	112597	Power Kw:	White
Bodytype:	Transporter	Body colour:	Opaque
Gearbox:	MAN 5 VIT	Paint type:	Black
Transmission:	Front	Interior colour:	Steel
Fueltype:	Diesel	Type of rims (mounted):	Black
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	2	Tow bar	
Number keys remote	1	Radio	
Windows electric F		Rear parking sensors	
Cruise Control		Sliding door right-side	
Type of climate control	Manual climate control	Seat cover lining	Lining Other

Tyres

	215/65/16/102 V			
Summer tyres:	Fr.L.	Hankook: 55%	Fr.R.	Hankook: 60%
	Re.L.	Hankook: 35%	Re.R.	Hankook: 40%
Tyre profile depth FL				4.5
Tyre profile depth FR				4.3
Tyre profile depth RL				5.8
Tyre profile depth RR				5.5
Tyre size FL				215/65 R 16 102 V
Tyre size FR				215/65 R 16 102 V
Tyre size RL				215/65 R 16 102 V
Tyre size RR				215/65 R 16 102 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Spare wheel	Yes	Jack	Yes
Backrest cover RM, Tear, Replace			



Inner door sill FL, Scratch(es), Paint



Door seal FL, Tear, Replace



Outside rear-view mirror housing L, Scratch(es), Replace



Side wall RL, Dent(s), Acceptable



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Acceptable



Bumper F, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Replace



Sliding door R, Dent(s), Repair and paint (complete)



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Rubber seal for boot lid, Tear, Replace



Rear floor trunk, Rust, Paint



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Number plate light R, Broken, Replace



Bodywork, Glue residues, Sticker removal small



Historique Maintenance

Immatriculation: FV-579-LW Date de 1ère immatriculation: 30/11/2020

Modèle: Citroen BERLINGO Taille M 1000kg BlueHDi 75 S&S BVM Club VU [4P] bvm 5-75CH-5cv (fourgonnettesimple cabine)

Date	Kilométrage	Fournisseur	Descriptif
03/03/2026	110.017	DUMAS AUTOMOBILES	POT CATALYTIQUE FAP RPLT
24/02/2025	94.338	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
20/02/2025	94.208	DUMAS AUTOMOBILES	DISQUES PLAQUETTES AV RPLT
31/01/2025	94.208	DUMAS AUTOMOBILES	DIVERS SUSPENSION
	0		LAMPE RPLT
	0		REVISION
	0		FILTRE CLIM RPLT
05/07/2023	58.520	GARAGE DU MIDI	ADBLUE
	0		ECLAIRAGE DE PLAQUE RPLT
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		PLAQUETTES AV RPLT
	0		PLAQUETTES AR RPLT
11/04/2022	30.711	DUMAS AUTOMOBILES	DISQUES PLAQUETTES AV RPLT
	0		REVISION