



MERCEDES A BERLINE

Vinnumber:	WDD1771031J176372	Versionname:	A 180 d DCT Launch Edition
First Registrationdate:	15/11/2019	Fiscalpower:	
Expertise Mileage:	125403	Power Kw:	85
Bodytype:		Body colour	Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3411
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

	205/55/17/91 W			
Summer tyres:	Fr.L.	Pirelli: 2 mm	Fr.R.	Pirelli: 1 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 4 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				1.0
Tyre profile depth RL				3.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 17 91 W
Tyre size FR				205/55 R 17 91 W
Tyre size RL				205/55 R 17 91 W
Tyre size RR				205/55 R 17 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1532,25
Bumper F, Scratch(es), Spot repair	148,33



Roof pillar L, Dent(s), Acceptable

0,00



Alloy rim FL, Scratch(es), Repair and paint (complete)

133,03



Door FL, Scratch(es), Repair and paint (complete)

445,79



Door RL, Dent(s) and scratch(es), Acceptable

0,00



Boot lid covering R, Worn, Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Tyre FR, Worn, Replace

180,98



Alloy rim FR, Scratch(es), Repair and paint (complete)

133,03




Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

491,09



Door RR, Scratch(es), Acceptable

0,00



Door FR, Dent(s) and scratch(es), Acceptable

0,00

