

Expertise

Protocol number: 46213966
Order No. / Reference: 26483890
Inspection date: 22 Jun 2026

Manufacturer: Opel

Model: Mokka-e Elegance

VIN: VXXKUKZKXZNW121532



Vehicle details

Manufacturer / Type / Model / Equipment

Opel Mokka-e Elegance

Vehicle Identification number VXXKUKZKXZNW121532

Mileage (Read) 61,169 km

First registration 19 Jun 2023

Number of holders 1

Power / Engine displacement 57 kw / 0 ccm

Fuel type / Cylinder Electric / 0

Gearbox / Number of gears Direct drive / 1

Type of drive Front drive

Type of vehicle SUV

Colour / colour code Jade Weiß

Doors / Seats 5 / 5

Upholstery type Cloth / leather combination

Colour of upholstery Grey-Anthracite



Equipment

Standard equipment

- 2 ignition keys, with remote control
- Storage compartments
- Driver and passenger side airbags
- Airbag: Head airbags, front and rear outer
- Active Pedestrian Warning System (AVAS)
- Electrically adjustable and heated exterior mirrors
- Exterior mirrors in black
- Hill Start Assist
- Braking system: Regenerative
- Headliner, Grey
- Decorative strips, silver
- Third brake light
- Electronic Stability Program Plus (ESP Plus)
- Electric windows front and rear
- Pedestrian protection
- Cruise control with intelligent speed limiter
- Rear shelf
- automatic climate control
- Rear headrests (3), height adjustable
- LED fog lights
- Steering wheel: Leather steering wheel, flattened at the bottom
- Makeup mirror in sun visor, driver and front passenger
- Multi-collision brake
- Fatigue detection
- Opel Connect with telematics services
- Parkpilot, rear parking aid, with acoustic warning signal when reversing.
- Wheels: Tire repair kit
- Keyless Start system
- Speed-sensitive power steering
- Visibility equipment
- Seats: Driver's seat 6-way manually adjustable
- Seats: Rear seat backrest foldable in a 60:40 ratio
- Lane Keeping Assist
- Start/Stop System
- Traction control with engine and brake intervention TC Plus
- Underride protection look, front and rear, in silver
- heat pump
- Central locking with remote control
- Storage: Pockets on the back of the front seats
- Adaptive brake light
- Airbag: Front and side airbags
- Actively controlled air intakes (Active Aero Shutter)
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Battery charging kit: Mode 2 charging cable (1.8 kW) for household socket and battery charging status indicator
- Roof design line in chrome
- Roof spoiler, black
- Double boot floor
- Electronic brake force distribution (EBD)
- Chassis: Driving modes
- Front collision warning with automatic city emergency braking and pedestrian detection
- Transmission: Automatic electric drive with fixed gear ratio
- Child safety lock in the rear doors, manual
- Headrests (2)
- Charging options
- LED headlights
- Steering column, height and tilt adjustable
- Reading lights, front
- Center armrest, front
- myOpel App
- Onboard charger (vehicle-integrated charging unit), 3-phase (11 kW)
- Upholstery: Fabric/Premium leather look
- Wheels: Light alloy (4) 5 double spokes 6.5 J x 17 in BiColor Black
- Side impact protection
- Seat belts
- Seats: Passenger seat 6-way manually adjustable
- Seats: Comfort seats, front
- Seats: Pre-installation for ISOFIX child seat mounting system, rear outer
- 12-volt power outlet
- Ambient lighting
- Traffic sign recognition
- Tinted heat-insulating glazing



Extra equipment

- Active Drive Assist Plus (Automatic Speed Assist with Stop & Go function - Front Collision Warning with automatic emergency braking as well as pedestrian and cyclist detection - Active Lane Keeping Assist)
- Paint finish: Uni Jade White
- Park & Go (Park Pilot, front and rear parking aid with audiovisual warning - 180-degree panoramic reversing camera - blind spot warning and side protection - electrically folding exterior mirrors - ambient lighting)
- Radio: Multimedia Navi (Mokka-e) (with 7" color touchscreen display and fully digital 7" driver information display - navigation system with integrated memory - road map of Europe (including Russia and Turkey) - 3D map display - dynamic route guidance via map and/or arrow display - display of points of interest - trip planning - GPS module - display of charging stations. OpelConnect, including LIVE navigation services: - map updates (via USB) - voice control for audio, telephone and navigation - radio, Bluetooth, DAB+, USB, hands-free calling.)
- Anti-theft alarm system (deterrent signal - interior monitoring)
- Floor mats, velour, 4-piece set
- IntelliLux LED Matrix Light (Adaptive LED matrix headlights with individual light distribution and the following functions: - City light - Highway light - Country road light - Static cornering light - Turning light - Parking light - High beam assistant: traffic-dependent dimming taking into account preceding and oncoming road users - Automatic headlight range control)
- Seats: Heated seats, multi-stage, driver and front passenger
- Solar Protect heat-insulating glazing (heavily tinted, in the rear)
- Universal Charger (1.8-22 kW, 3-phase) with 3 adapters for: - Household socket - Public charging - CEE-16 industrial socket (three-phase) - incl. storage bag)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Interior	Interior - Soiled - No deduction
5	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Side right, Underbody, Provided by user / customer, from 12 Jul 2024	2.268,00 €



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VXXKUKZKXZNW121532
Hersteller / Modell: OPEL OPEL Mokka-e Elegance

Datum	KM-Stand	Beschreibung
04.05.2026	61.112	Batterie ern; Systemtest/Eigendiagnose
08.07.2025	57.140	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst
11.06.2024	37.149	Regelwartungsdienst
23.11.2023	12.987	Regelwartungsdienst