

Volkswagen Caddy 2.0 TDI L2H1 BMT Maxi (Bestel) | Trekhaak | Cruise |

Contact Summary

License plate	V-189-SL	Fuel	Diesel
VIN	WV1ZZZ2KZX018825	Transmission	Manual
Brand	Volkswagen	Doors	4
Model	Caddy	Seats	2
Model Type	2.0 TDI L2H1 BMT Maxi (Bestel) ...	Color	White
VAT/Margin	VAT	Interior Color	Black
Mileage	80745 Km	Interior Type	Fabric
Expected mileage	80745 Km	Paint type	
Available per	Direct	NAP status	Logical

Vehicle Details

History				Environment	
Manufacture year	2019	Model year	15-04-2015 → 31-12-2020	Energy label	
First registration	01-02-2019 (NL)	Used as	Normal	CO2 emission (NEDC)	127
Current registration	01-02-2019 (NL)	Immigration good	No	EU category	Euro 6
Imported	No	Vehicle Source	Dealer		

Engine & performance		Financial		Weights	
Power	75 kw	BPM deductible	No	Empty weight	2299
Cylinders	4	Gross BPM	€ 8084	Towing weight	0
Engine	1968	Rest BPM	€ 2021	Wheel base	301
Drivetrain	Frontwheeldri...				

Remark	
Parking Location	E12
Resterende stickers	

Features

Specific features		
Passenger seat height adjustable	Body colored bumpers	features.vering verzwaard
Radio	Central locking with remote control	Rear doors with windows
Rain sensor	Comfort seat(s)	Rear window heating
Heated windshield washers/wiper blades	Cruise control	Rear window wiper
Start/stop system	Dipped beam automatically	Air conditioning
Leather multifunction steering wheel	Electric windows in front	Alarm class 1 (immobilizer)
Power steering	Electronic limited slip differential	Anti blocking system
Partition complete	Electronic Stability Program	Anti-slip Regulation
Unicolour/pastel	Hill hold function	Driver's airbag
Tiredness recognition	Front head airbag(s).	Driver's seat adjustable in height
Subsequent collision prevention	Adjustable lumbar support	Interior mirror automatically dimming
Heated windshield	Alloy wheels 15"	On-board computer
Heat-resistant glass	Front fog lights adaptive	Brake Assist System
Front side airbag(s).	Rear parking sensor	Exterior mirrors electrically adjustable and hea...
Sliding side door on the right	Passenger airbag	Exterior mirrors in body color

Packages

Conditions

Optical issues

Restyle dent(s)	
Rear left screen	
Scratch(es)	
Rear bumper	
Dent(s)	
Threshold right	
Scratch(es)	
A-pillar right	
createpage.OpticalDamages.Description.Cl...	
All-round vehicle	
Corrosion	
Roof	

Technical inspection & maintenance

Technical inspection	21-05-2027	Keys	1
Maintenance history	Incomplete	Driveable	Yes
Last date of maintenance	26-10-2021		
Odorless	Yes		

Tyres

AllSeason	Good (4/4/5/5)
-----------	----------------

Owner history

Date	Extra info	Owner	Number Of Days
27-09-2018		Importeur	127
01-02-2019	Eerste toelating Datum deel IA / I	Lease/verhuur	2698
22-06-2026	Laatste tenaamstelling	Lease	16
21-05-2027	APK vervaldatum		-

Summary



Volkswagen Caddy 2.0 TDI L2H1 BMT Maxi (Bestel) | Trekhaak | Cruise |

Licence plate	V-189-SL	Technical damage	No
Mileage	80745 Km	Optical damage	Yes
Expected Mileage	80745 Km	Nr of Owners	3
Available per	08-07-2026	Used as	Normal
Transmission	Manual	BPM Reclaimable	No
Drivetrain	Frontwheeldrive	Catalog	Continuous
Power	75	Lot ID	7ac52b80-6a65-...
VAT/Margin	VAT	Date	08-07-2026
NAP status	Logical	Remark	Yes
Manufacture year	2019		
Imported	No		
Country of origin	NL		