



Peugeot 208 (UKL): 2CFN943

Vinnumber:	VR3UPHNEKNT074383	Versionname:	208 GT 1.2 PureTech S&S 100pk/cv 5p
First Registrationdate:	5/07/2022	Fiscalpower:	
Expertise Mileage:	11375	Power Kw:	74
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	NOT OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/45/17/88 H			
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				205/45 R 17 88 H
Tyre size FR				205/45 R 17 88 H
Tyre size RL				205/45 R 17 88 H
Tyre size RR				205/45 R 17 88 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	No	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Service, Maintenance, Check



Bumper F, Scratch(es), Spot repair



Tyre RL, Tear, Replace



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Tyre FL, Tear, Replace



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Door RL, Dent(s), Acceptable



Reflector, Scratch(es), Replace



Bumper moulding R, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Acceptable



Kenteken	2CFN943
Merk Model	Peugeot 208 GT 1.2 PureTech S&S 100pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	7/5/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/24/25	8,063	luchtfilter interieur	Vervangen
6/24/25	8,063	oliezeef	Vervangen
6/24/25	8,063	onderhoud 3e jaar	Uitvoeren
5/6/24	5,250	luchtfilter interieur	Vervangen
5/6/24	5,250	oliezeef	Vervangen
5/6/24	5,250	onderhoud 1e jaar	Uitvoeren
5/6/24	5,250	remvloeistof	Vervangen