MACADAM







Peugeot Partner (Segm. B1): 2AFD952

Vinnumber:	**VR3EFYHZRLJ965853**	Versionname:	**Partner L2 Heavy Premium 1.5 BlueHDi S&S 130pk/cv EAT8**
First Registrationdate:	**16/03/2021**	Fiscalpower:	
Expertise Mileage:	**112151**	Power Kw:	**96**
Bodytype:		Type of rims (mounted)	**Steel**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**NOT OK**		
Maintenance	**min 72140 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Light Commercial Vehicle**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**1**	Type of Tow bar	**Tow bar fixed**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**N.A.**		

Tyres

Summer tyres:	**205/60/16/96 H**			
	Fr.L.	**Michelin: 5 mm**	Fr.R.	**Bridgestone: 5 mm**
	Re.L.	**Bridgestone: 4 mm**	Re.R.	**Bridgestone: 4 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**205/60 R 16 96 H**
Tyre size FR	**205/60 R 16 96 H**
Tyre size RL	**205/60 R 16 96 H**
Tyre size RR	**205/60 R 16 96 H**
Tyre type FL	**Summer**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**261**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Service, Maintenance, Check




Ignition key, Missing, Replace



Seat cover FL, Stain, Cleaning




Bumper F, Scratch(es), Replace






Windscreen, Scratch(es), Replace







Wing FL, Dent(s) and scratch(es), Acceptable





Outside rear-view mirror housing L, Scratch(es), Acceptable




Wing RL, Dent(s) and scratch(es), Acceptable





Tyre FL, Not original part, Replace





Wheel aperture RR, Scratch(es), Acceptable




Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)







Boot door panel RR, Dent(s), Acceptable




Bumper R, Scratch(es), Acceptable




Wing RR, Dent(s), Acceptable






Outside rear-view mirror housing R, Scratch(es), Acceptable




Wing FR, Dent(s), Acceptable




Aerial, Deformed / Strained, Replace




Onderhoudshistorie van: VR3EFYHZRLJ965853

ALPHABET

Kenteken	2AFD952
Merk Model	Peugeot Partner L2 Heavy Premium 1.5 BlueHDi S&S 130pk/cv EAT8
Brandstofsoort	Diesel
Datum deel1	3/16/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
11/20/25	102,108	diagnose	Uitvoeren
6/23/25	90,709	onderhoud 4e jaar	Uitvoeren
6/23/25	90,709	remblokken vooraan	Vervangen
6/23/25	90,709	remvloeistof	Vervangen
6/23/25	90,709	riem of multiriem	Vervangen
6/23/25	90,709	ruitenwisserrubber vooraan	Vervangen
3/13/25	83,442	AdBlue injector	Vervangen
3/13/25	83,442	diagnose	Uitvoeren
3/13/25	83,442	ruitenwisserrubber vooraan	Vervangen
10/30/24	72,503	halogeenlamp	Vervangen
10/15/24	71,006	halogeenlamp	Vervangen
8/26/24	68,455	80000 km	Uitvoeren
8/26/24	68,455	brandstof hoofdfilter	Vervangen
8/26/24	68,455	luchtfilter	Vervangen
8/26/24	68,455	luchtfilter interieur	Vervangen
8/26/24	68,455	oliezeef	Vervangen
8/26/24	68,455	universele lampen	Vervangen
3/18/24	56,839	universele lampen	Vervangen
9/18/23	50,121	accu	Vervangen
9/18/23	50,121	diagnose	Uitvoeren
8/7/23	50,121	diagnose	Uitvoeren
10/3/22	30,210	oliewissel	Vervangen
10/3/22	30,210	oliezeef	Vervangen