



Volkswagen Tiguan (KKL): 2ACV406

Vinnumber:	WVGZZZ5NZMM057270	Versionname:	Tiguan Allspace Comfortline 1.5TSi ACT 150pk/cv 5p DSG7
First Registrationdate:	23/02/2021	Fiscalpower:	
Expertise Mileage:	205867	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	over 5100 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

215/65/17/99 V				
Summer tyres:	Fr.L.	Firestone: 5 mm	Fr.R.	Firestone: 5 mm
	Re.L.	Firestone: 5 mm	Re.R.	Firestone: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/65 R 17 99 V
Tyre size FR				215/65 R 17 99 V
Tyre size RL				215/65 R 17 99 V
Tyre size RR				215/65 R 17 99 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				258
Tyre make FR				258
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

MOT certificate, Non-conforme, Replace



Floor covering FL, Hole, Smart repair



Door panel RL, Scratch(es), Acceptable



Backrest cover RL, Scratch(es), Acceptable



Backrest cover RR, Scratch(es), Acceptable



Door panel RR, Scratch(es), Acceptable



Windscreen, Stone chip(s), Acceptable



Bonnet, Stone chip(s), Acceptable



Bumper F, Scratch(es), Repair and paint (complete)





Bumper spoiler F, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Door RL, Dent(s), Paintless dent repair



Alloy rim FL polished, Scratch(es), Acceptable



Door trim FL, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Boot carpet, Stain, Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Bumper trim R, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Acceptable





Wing RR, Dent(s) and scratch(es), Acceptable



Door RR, Dent(s), Acceptable



Door FR, Dent(s), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Acceptable



Kenteken	2ACV406
Merk Model	Volkswagen Tiguan Allspace Comfortline 1.5TSi ACT 150pk/cv 5p DSG7
Brandstofsoort	Benzine
Datum deel1	2/23/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/28/26	191,397	halogeenlamp	Vervangen
2/28/26	191,397	klein materiaal	
10/8/25	176,241	diagnose	Uitvoeren
10/8/25	176,241	Inspectie met olie vervanging (vast in	Uitvoeren
10/8/25	176,241	klein materiaal	
10/8/25	176,241	luchtfilter	Vervangen
10/8/25	176,241	luchtfilter interieur	Vervangen
10/8/25	176,241	remblokken achter	Vervangen
10/8/25	176,241	remblokken vooraan	Vervangen
10/8/25	176,241	remvloeistof	Vervangen
10/8/25	176,241	riem of multiriem	Vervangen
10/8/25	176,241	ruitenwisserrubber achter	Vervangen
10/8/25	176,241	ruitenwisserrubber vooraan	Vervangen
9/26/24	145,579	airco systeem reiniging	Uitvoeren
9/26/24	145,579	batterij	Vervangen
9/26/24	145,579	bougie	Vervangen
9/26/24	145,579	klein materiaal	
9/26/24	145,579	koelwatervloeistof	Vervangen
9/26/24	145,579	luchtfilter interieur	Vervangen
9/26/24	145,579	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
9/26/24	145,579	ruitenwisserrubber achter	Vervangen
9/26/24	145,579	ruitenwisserrubber vooraan	Vervangen
9/26/24	145,579	ruitenwisservloeistof	Bijvullen/-laden
9/26/24	145,579	versnellingsbakolie	Vervangen
9/26/24	145,579	waterafvoer open dak	Reinigen
8/23/23	100,524	batterij	Vervangen
8/23/23	100,524	Inspectie met olie vervanging (vast in	Uitvoeren
8/23/23	100,524	klein materiaal	
8/23/23	100,524	koelwatervloeistof	Bijvullen/-laden
8/23/23	100,524	luchtfilter	Vervangen
8/23/23	100,524	remschijven en blokken achter	Vervangen
8/23/23	100,524	remschijven en blokken vooraan	Vervangen
8/23/23	100,524	ruitenwisserrubber achter	Vervangen
8/23/23	100,524	ruitenwisserrubber vooraan	Vervangen
8/23/23	100,524	ruitenwisservloeistof	Bijvullen/-laden
8/23/23	100,524	schuif/ -kanteldak	Reinigen
1/2/23	71,988	bougie	Vervangen
1/2/23	71,988	Inspectie met olie vervanging (vast in	Uitvoeren
1/2/23	71,988	klein materiaal	
1/2/23	71,988	luchtfilter interieur	Vervangen

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
1/2/23	71,988	remvloeistof	Vervangen
1/2/23	71,988	ruitenwisservloeistof	Bijvullen/-laden
1/2/23	71,988	waterafvoer open dak	Reinigen
9/6/22	56,188	controle niveaus	Uitvoeren
9/6/22	56,188	olie bijvullen	Uitvoeren
9/6/22	56,188	ruitenwisservloeistof	Uitvoeren
2/18/22	34,024	batterij	Vervangen
2/18/22	34,024	Inspectie met olie vervanging (vast in	Uitvoeren
2/18/22	34,024	klein materiaal	
2/18/22	34,024	koelwatervloeistof	Bijvullen/-laden
2/18/22	34,024	ruitenwisserrubber achter	Vervangen
2/18/22	34,024	ruitenwisserrubber vooraan	Vervangen
2/18/22	34,024	ruitenwisservloeistof	Bijvullen/-laden
2/18/22	34,024	waterafvoer open dak	Reinigen