MACADAM










Volkswagen Up: L792SP

Vinnumber:	**WVWZZZAAZND003208**	Versionname:	**Up 1.0 48kW**
First Registrationdate:	**21/10/2021**	Fiscalpower:	
Expertise Mileage:	**122424**	Power Kw:	**48**
Bodytype:		Body colour	**Pure White Unilak**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Steel**
Fueltype:	**Petrol**	Parking lot	**387**
Number of seats	**4**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS		Rear view camera	
Autom climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	175 / 65 / 14 / 86 / H / Steel	7,2 mm	Continental	All season
	Right	175 / 65 / 14 / 86 / H / Steel	7,0 mm	Continental	All season
Rear	Left	175 / 65 / 14 / 86 / H / Steel	7,0 mm	Continental	All season
	Right	175 / 65 / 14 / 86 / H / Steel	7,0 mm	Continental	All season

Assistance equipment

Door RL, Scratch(es), Polish




Door FL, Scratch(es), Polish




Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)





Bonnet, Stone chip(s), Repair and paint (complete)






Tailgate / Boot, Not original part, Remove lettering



Rear spoiler, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Repair and paint (complete)







Roof, Scratch(es), Repair and paint (complete)







Onderhoudshistorie van: WVWZZZAAZND003208

ALPHABET

Kenteken	L792SP
Merk Model	Volkswagen Up 1.0 48kW
Brandstofsoort	Benzine
Datum deel1	10/21/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
4/7/26	108,545	Onderhoudsbeurt
4/7/26	108,545	Remblokken voorzijde
4/7/26	108,545	Remtrommel
4/7/26	108,545	Vervanging band
9/16/25	96,205	APK
9/16/25	96,205	Onderhoudsbeurt
9/16/25	96,205	Remvloeistof
9/16/25	96,205	Wiellager voor
3/4/25	81,874	Aandrijfashoes
3/4/25	81,874	Onderhoudsbeurt
3/4/25	81,874	Ruitenwisserblad(en) achterzijde
3/4/25	81,874	Ruitenwisserblad(en) voorzijde
3/4/25	81,874	Vervanging band
10/23/24	73,570	Sleutelbatterij
5/23/24	63,965	Bougie
5/23/24	63,965	Luchtfilter
5/23/24	63,965	Onderhoudsbeurt
5/23/24	63,965	Vervanging band
2/21/24	55,304	Reparatie band(en)
10/6/23	45,874	Onderhoudsbeurt
10/6/23	45,874	Remvloeistof
10/6/23	45,874	Ruitenwisserblad(en) voorzijde
1/2/23	29,104	Onderhoudsbeurt
1/2/23	29,104	Ruitenwisserblad(en) achterzijde
1/2/23	29,104	Ruitenwisserblad(en) voorzijde
4/6/22	14,470	Onderhoudsbeurt