



# Mercedes GLC:

|                                   |                   |                        |           |
|-----------------------------------|-------------------|------------------------|-----------|
| Vinnumber:                        | W1N2533111F981513 | Versionname:           |           |
| First Registrationdate:           | 12/08/2021        | Fiscalpower:           |           |
| Expertise Mileage:                | 82597             | Power Kw:              |           |
| Bodytype:                         |                   | Body colour            | Grey      |
| Gearbox:                          | Automatic         | Type of rims (mounted) | Aluminium |
| Transmission:                     |                   | Parking lot            | 2515      |
| Fueltype:                         | Hybrid Diesel     |                        |           |
| Type of rims (mounted)            | Aluminium         |                        |           |
| Certificate of Conformity         | Yes               |                        |           |
| Category                          | Passenger Car     |                        |           |
| Registration Certificate Car (BE) | Yes               |                        |           |

## Options

|                                |                       |                       |            |
|--------------------------------|-----------------------|-----------------------|------------|
| Number of keys total           | 2                     | Seats electric F L    |            |
| Cruise Control                 |                       | Seats electric F R    |            |
| Steering wheel multifunctional |                       | Sun Roof electric     |            |
| Seats F heated                 |                       | Luggage cover         |            |
| Radio multimedia               |                       | Front parking sensors |            |
| Type of headlighting           | Headlighting LED      | Rear parking sensors  |            |
| Type of GPS                    | GPS big screen color  | Type of Tow bar       | No Tow bar |
| Type of Lining                 | Lining leather        |                       |            |
| Type of climate control        | Autom climate control |                       |            |
| Adaptive cruise control        |                       |                       |            |
| Type of GPS storage            | HD                    |                       |            |

## Limited Technical Inspection

### Tyres

|                       |       |                   |       |                   |
|-----------------------|-------|-------------------|-------|-------------------|
| 235/60/18/103 V       |       |                   |       |                   |
| Summer tyres:         | Fr.L. | Bridgestone: 3 mm | Fr.R. | Bridgestone: 3 mm |
|                       | Re.L. | Bridgestone: 3 mm | Re.R. | Bridgestone: 3 mm |
| Tyre profile depth FL |       |                   |       | 3.0               |
| Tyre profile depth FR |       |                   |       | 3.0               |
| Tyre profile depth RL |       |                   |       | 3.0               |
| Tyre profile depth RR |       |                   |       | 3.0               |
| Tyre size FL          |       |                   |       | 235/60 R 18 103 V |
| Tyre size FR          |       |                   |       | 235/60 R 18 103 V |
| Tyre size RL          |       |                   |       | 235/60 R 18 103 V |
| Tyre size RR          |       |                   |       | 235/60 R 18 103 V |
| Tyre type FL          |       |                   |       | Summer            |
| Tyre type FR          |       |                   |       | Summer            |
| Tyre type RL          |       |                   |       | Summer            |
| Tyre type RR          |       |                   |       | Summer            |
| Tyre make FL          |       |                   |       | 255               |
| Tyre make FR          |       |                   |       | 255               |
| Tyre make RL          |       |                   |       | 255               |
| Tyre make RR          |       |                   |       | 255               |

## Assistance equipment

|                                          |     |            |     |
|------------------------------------------|-----|------------|-----|
| Repair kit                               | Yes | Compressor | Yes |
| Number of charging cables (normal)       | 1   |            |     |
| Number of charging cables (rapid charge) | 1   |            |     |

|                                                                       |        |
|-----------------------------------------------------------------------|--------|
| Total cost ex VAT                                                     | 422,44 |
| Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete) | 422,44 |



Alloy rim RR polished, Scratch(es), Acceptable

0,00

