


**Vehicle details**

VIN	VXKUPHNKS P4145581	Registration date	17/08/2023	Exterior Color	Unknown
Brand	OPEL	Licence Plate		Odometer	38 336 km
Model	CORSA 1.2 Direct Inj Turbo 74kW Elegance				

**Inspection Details**

Arrival Date	17/03/2026	Inspection ID	6891732	Inspection date	15/04/2026
Assign Date	17/03/2026	Fleet owner		Inspection loc.	



**Generic equipment**

--


**Removable element**

Spare wheel kit	✓
Rear parcel shelf	✓
Radio user manual	✓

**Technical Document**

User manual	✓
Log books	✓
Spare key	✓
Key	✓
Warranty booklet	✗
Service	✗

**Tyres**




Goodyear 195/55/16 H All seasons 5.0 mm

Goodyear 195/55/16 H All seasons 5.0 mm






Goodyear 195/55/16 H All seasons 5.0 mm

Goodyear 195/55/16 H All seasons 5.0 mm

**Exception / Damage**

	Part	Warranty booklet	Repair Time	-	Part Cost	50.00€
	Position		Repair Cost	-	Gross Cost	50.00€
	Damages	Missing	Paint Time	-	Depreciation %	-
	Severity		Paint cost	-	Depreciation	-
	Repair mode	Replace	Flat Rate	-	<b>Net Cost</b>	<b>50.00€</b>
	Falsche FIN im Serviceheft					

**DEKRA Automotive Solutions**

2		Part	Service	Repair Time	-	Part Cost	150.00€
		Position	-	Repair Cost	-	Gross Cost	150.00€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	<b>Net Cost</b>	<b>150.00€</b>
3		Part	Bumper	Repair Time	-	Part Cost	-
		Position	Front	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	15.00%
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	<b>Net Cost</b>	-
4		Part	Bonnet	Repair Time	-	Part Cost	-
		Position	Front	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	15.00%
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	<b>Net Cost</b>	-
5		Part	Windscreen	Repair Time	-	Part Cost	-
		Position	Front	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	<b>Net Cost</b>	-
6		Part	Service 2	Repair Time	-	Part Cost	200.00€
		Position	-	Repair Cost	-	Gross Cost	200.00€
		Damages	Missing	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	<b>Net Cost</b>	<b>200.00€</b>

**Summary Inspection**

Gross Price	400.00€	Depreciation	-	Net Price	400.00€
-------------	---------	--------------	---	-----------	---------

**Labor cost summary**

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	0.00€	0.00	0.00€	-	-	0.00€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

**Miscellaneous**

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	400.00€	-	-	400.00€
Flat Rate	-400.00€	-	-	-400.00€