MACADAM









RENAULT TRAFIC: FV-915-DV

Vinnumber:	**VF1FL000666072746**	Versionname:	**RENAULT TRAFIC NV FG GCF L2H1 1300 dCi 120 VU [4P] bvm 6-120CH-7cv (fourgon tÃ´lÃ©simple cabine)**
First Registrationdate:	**17/11/2020**	Fiscalpower:	
Expertise Mileage:	**133387**	Power Kw:	**88**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**5**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Rear parking sensors	
Windows electric F		Roof bar black	
Cruise Control		Sliding door right-side	
Type of climate control	**Manual climate control**	Seat cover lining	**Lining Other**

Tyres

Summer tyres:	**205/65/16/107 T**			
	Fr.L.	**Uniroyal: 40%**	Fr.R.	**Uniroyal: 40%**
	Re.L.	**Uniroyal: 20%**	Re.R.	**Uniroyal: 40%**

Tyre profile depth FL	**5.7**
Tyre profile depth FR	**5.5**
Tyre profile depth RL	**6.9**
Tyre profile depth RR	**5.6**
Tyre size FL	**205/65 R 16 107 T**
Tyre size FR	**205/65 R 16 107 T**
Tyre size RL	**205/65 R 16 107 T**
Tyre size RR	**205/65 R 16 107 T**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**265**
Tyre make FR	**265**
Tyre make RL	**265**
Tyre make RR	**265**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Outside rear-view mirror base L, Broken, Replace



Side panel L, Hail damage, Repair and paint (complete)






Outer sill L, Dent(s), Repair and paint (complete)




Bonnet, Hail damage, Repair and paint (complete)






Side wall RR, Dent(s), Acceptable




Bumper corner RL, Scratch(es), Acceptable




Bumper R, Deformed / Strained, Repair and paint (complete)






Rear light R, Waterinfiltration, Replace




Boot door panel RL, Hail damage, Repair and paint (complete)








Boot door panel RR, Hail damage, Repair and paint (complete)





Roof, Hail damage, Repair and paint (complete)








Bodywork, Not original part, Sticker removal small




ALPHABET

Historique Maintenance

Immatriculation: **FV-915-DV** Date de 1ère immatriculation: **17/11/2020**

Modèle: **Renault TRAFIC NV FG GCF L2H1 1300 dCi 120 VU [4P] bvm 6-120CH-7cv (fourgon tôlésimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
06/05/2026	123.646	CONTITRADE FRANCE LA CROIX ST OUEN	PERMUTATIONS PNEUS
27/02/2026	119.139	SIMONNEAU AUTOMOBILES	DIVERS ELEC
	0		DIVERS ELEC
14/01/2026	116.346	SIMONNEAU AUTOMOBILES	REVISION ET CLIM
	0		PLAQUETTES AV RPLT
	0		BALAIS ESSUIE GLACE AV
13/01/2026	115.415	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER
14/11/2025	112.609	ROGER	ANTIPOLLUTION
02/06/2025	102.911	CONTITRADE FRANCE	PERMUTATIONS PNEUS
	0		GARDIENNAGE
27/11/2024	90.640	CONTITRADE FRANCE	GARDIENNAGE
07/11/2024	89.516	ROGER	CONTROLE TECHNIQUE
05/04/2024	79.126	SIMONNEAU AUTOMOBILES	BALAIS ESSUIE GLACE AV
	0		DISQUES PLAQUETTES AV RPLT
	0		PILE DE CLE RPLT
	0		DISQUES PLAQUETTES AR RPLT
	0		REVISION ET CLIM
	0		REVISION
	0		ADBLUE
26/03/2024	75.216	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE
09/02/2024	73.140	SIMONNEAU AUTOMOBILES	BATTERIE RPLT
29/01/2024	66.648	SIMONNEAU AUTOMOBILES	TELECHARGEMENT CALCULATEUR
14/12/2022	49.320	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER
02/09/2022	41.671	SIMONNEAU AUTOMOBILES	REVISION
	0		PLAQUETTES AV RPLT
	0		BALAIS ESSUIE GLACE AV