



Opel Corsa: N948SL

Vinnumber:	VXKHZKXZM4325850	Versionname:	Corsa-E 3 fase lader 100kW / 50kWh Edition
First Registrationdate:	24/12/2021	Fiscalpower:	
Expertise Mileage:	50583	Power Kw:	100
Bodytype:		Body colour:	White Jade
Gearbox:	Automatic	Paint type:	Opaque
Transmission:		Type of rims (mounted):	Steel
Fueltype:	Electric	Parking lot:	1038
Number of seats:	5		
Type of rims (mounted):	Steel		
Maintenance needed:	No		

Options

Number of keys total	2
Autom climate control	
Radio multimedia	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 55 / 16 / 87 / H / Steel	3,1 mm	Goodyear	All season
	Right	195 / 55 / 16 / 87 / H / Steel	4,0 mm	Goodyear	All season
Rear	Left	195 / 55 / 16 / 87 / H / Steel	5,0 mm	Goodyear	All season
	Right	195 / 55 / 16 / 87 / H / Steel	4,2 mm	Goodyear	All season

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Roof liner, Stain, Cleaning



Bumper F, Scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Smart repair



Tailgate / Boot, Scratch(es), Polish



Kenteken	N948SL
Merk Model	Opel Corsa-E 3 fase lader 100kW / 50kWh Edition
Brandstofsoort	Elektrisch
Datum deel1	24-12-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
07-11-25	36.498	APK
07-11-25	36.498	Raam mechanisme
06-08-25	29.893	Onderhoudsbeurt
25-06-24	46.909	Boordcomputer
25-06-24	46.909	Onderhoudsbeurt
25-06-24	46.909	Remvloeistof
25-06-24	46.909	Tractie batterij lader
01-09-23	9.435	Onderhoudsbeurt