MACADAM








Audi A3 (UKL): 2CEY778

Vinnumber:	**WAUZZZGY8NA099694**	Versionname:	**A3 Sportback 40 1.4TFSi-e 204pk/cv 5p S-Tronic**
First Registrationdate:	**29/06/2022**	Fiscalpower:	
Expertise Mileage:	**65710**	Power Kw:	**110**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**in 23300 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/55/16/94 V**			
	Fr.L.	**Bridgestone: 5 mm**	Fr.R.	**Bridgestone: 5 mm**
	Re.L.	**Bridgestone: 5 mm**	Re.R.	**Bridgestone: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**205/55 R 16 94 V**
Tyre size FR	**205/55 R 16 94 V**
Tyre size RL	**205/55 R 16 94 V**
Tyre size RR	**205/55 R 16 94 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**0**		
Number of charging cables (rapid charge)	**1**		

Interior, No damage, Acceptable




Bumper F, Scratch(es), Acceptable




Bonnet, Stone chip(s), Acceptable




Bumper moulding F, Scratch(es), Acceptable




Alloy rim RL, Scratch(es), Acceptable




Charging cable (normal), Missing, Check



Bumper R, Scratch(es), Repair and paint (complete)






Tailgate / Boot, Dent(s), Paintless dent repair






Alloy rim RR, Scratch(es), Repair and paint (complete)





Outside rear-view mirror housing R, Scratch(es), Acceptable




Alloy rim FR, Scratch(es), Acceptable





Onderhoudshistorie van: WAUZZZGY8NA099694

ALPHABET

Kenteken	2CEY778
Merk Model	Audi A3 Sportback 1.4TFSi-e 204pk/cv 5p S-Tronic
Brandstofsoort	Benzine
Datum deel1	6/29/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
9/25/25	58,914	bougie	Vervangen
9/25/25	58,914	Inspectie met olieververvanging (vast in	Uitvoeren
9/25/25	58,914	instelling koplampen	Afstellen
9/25/25	58,914	klein materiaal	
9/25/25	58,914	remblokken vooraan	Vervangen
9/25/25	58,914	remvloeistof	Vervangen
9/25/25	58,914	ruitenwisserrubber achter	Vervangen
9/25/25	58,914	ruitenwisserrubber vooraan	Vervangen
9/25/25	58,914	versnellingsbakolie	Vervangen
3/19/24	30,241	Inspectie met olieververvanging (vast in	Uitvoeren
3/19/24	30,241	klein materiaal	
3/19/24	30,241	luchtfilter interieur	Vervangen
3/19/24	30,241	ruitenwisservloeistof	Bijvullen/-laden
7/20/23	15,123	klein materiaal	
7/20/23	15,123	koelwatervloeistof	Bijvullen/-laden
7/20/23	15,123	ruitenwisservloeistof	Bijvullen/-laden
7/20/23	15,123	Tussentijds onderhoud (vast interval)	Uitvoeren