MACADAM









OPEL CORSA: GP-752-KG

Vinnumber:	**VXKUBYHTKN4326761**	Versionname:	**OPEL CORSA 1.5 Diesel 100ch Edition VP [5P] bvm 6-102CH-5cv (bi-corps)**
First Registrationdate:	**8/06/2023**	Fiscalpower:	
Expertise Mileage:	**85436**	Power Kw:	**75**
Bodytype:	**Berline**	Body colour	**Grey**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Grey**
Fueltype:	**Petrol**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**1**	Luggage cover	
Windows electric F		Seat cover lining	**Lining Other**
Steering wheel multifunctional			
Type of climate control	**Manual climate control**		

Tyres

	195/55/16/91 H			
Winter tyres:	Fr.L.	**Dunlop: 80%**	Fr.R.	**Dunlop: 75%**
	Re.L.	**Dunlop: 20%**	Re.R.	**Dunlop: 35%**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.3**
Tyre profile depth RL	**6.9**
Tyre profile depth RR	**5.9**
Tyre size FL	**195/55 R 16 91 H**
Tyre size FR	**195/55 R 16 91 H**
Tyre size RL	**195/55 R 16 91 H**
Tyre size RR	**195/55 R 16 91 H**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**257**
Tyre make FR	**257**
Tyre make RL	**257**
Tyre make RR	**257**

Assistance equipment

Seat cover R, Dirty, Cleaning








Floor mat F, Tear, Repair/replace (lump sum)




Roof liner, Burned, Smart repair




Tyre FR, Out of tolerance, Replace






Tyre RR, Out of tolerance, Replace





Tyre RL, Out of tolerance, Replace





Tyre FL, Out of tolerance, Replace






Wing RR, Scratch(es), Paint




Door RR, Scratch(es), Paint




Wing FR, Dent(s), Repair and paint (complete)




Rear light L, Scratch(es), Replace




Bumper R, Scratch(es), Paint








ALPHABET

Historique Maintenance

Immatriculation: **GP-752-KG** Date de 1ère immatriculation: **08/06/2023**

Modèle: **Opel CORSA 1.5 Diesel 100ch Edition VP [5P] bvm 6-102CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
18/09/2026	83.353	BELLANGER	BALAIS ESSUIE GLACE AV
			REVISION ET CLIM
24/09/2025	52.616	STELLANTIS &YOU FRANCE SAS	REVISION ET CLIM ET AIR ET CARBURANT
			LIQUIDE DE FREIN
			BALAIS ESSUIE GLACE AV
			DISQUES PLAQUETTES AV RPLT
22/11/2024	25.286	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS HIVER
10/10/2024	20.628	STELLANTIS &YOU FRANCE SAS	REVISION ET CLIM
			BALAIS ESSUIE GLACE AV AR
23/04/2024	5.881	AERO 91	REVISION
24/10/2023	768	CONTITRADE FRANCE	REPARATION DE ROUE