



RENAULT CLIO: GD-898-EL

Vinnumber:	VF1RJA00167891019	Versionname:	RENAULT CLIO Business E-Tech hybride 140 -21N
First Registrationdate:	26/11/2021	Fiscalpower:	VP [5P] bva 6-140CH-5cv (bi-corps)
Expertise Mileage:	90668	Power Kw:	103
Bodytype:	Berline	Body colour:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Hybrid	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Rear parking sensors	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	195/55/16/87 H			
Summer tyres:	Fr.L.	Continental: 45%	Fr.R.	Continental: 45%
	Re.L.	Continental: 40%	Re.R.	Continental: 40%
Tyre profile depth FL	5.4			
Tyre profile depth FR	5.1			
Tyre profile depth RL	5.7			
Tyre profile depth RR	5.5			
Tyre size FL	195/55 R 16 87 H			
Tyre size FR	195/55 R 16 87 H			
Tyre size RL	195/55 R 16 87 H			
Tyre size RR	195/55 R 16 87 H			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	256			
Tyre make FR	256			
Tyre make RL	256			
Tyre make RR	256			

Assistance equipment

Remote ignition key, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Interior, Stain, Cleaning



Armrest F M, Broken, Replace



Wheel cover FL, Missing, Replace



Wing FL, Dent(s), Repair and paint (complete)



Outside rear-view mirror housing L, Missing, Replace and paint



Outside rear-view mirror base L, Broken, Replace



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Headlight R, Broken, Replace



Windscreen, Broken, Replace




Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Wing FR, Dent(s) and scratch(es), Replace and paint



Outside rear-view mirror housing R, Scratch(es), Paint



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Luggage compartment cover, Missing, Replace



Bumper R, Broken, Repair and paint (complete)



Bodywork, Not original part, Sticker removal small



Historique Maintenance

Immatriculation: **GD-898-EL** Date de 1ère immatriculation: **26/11/2021**

Modèle: **Renault CLIO Business E-Tech hybride 140 -21N VP [5P] bva 6-140CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
19/03/2026	86.072	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
04/11/2025	77.415	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE
	0		REPLACEMENT PNEUS ETE
20/10/2025	76.964	RENAULT RETAIL GROUP	REVISION
	0		RECYCLAGE
	0		FILTRE CLIM RPLT
23/04/2025	65.176	RENAULT RETAIL GROUP	BOITIER D ALLUMAGE RPLT
	0		SERENITE
	0		LIQUIDE DE FREIN
	0		FILTRE A AIR RPLT
	0		RECYCLAGE
13/12/2024	55.022	RENAULT RETAIL GROUP	POSE EQUILIBRAGE ROUES
	0		JANTE RPLT
28/09/2024	54.993	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
02/09/2024	54.126	SAS GARAGE DU ROURET	JANTE RPLT
	0		REPLACEMENT PNEUS ETE
	0		POSE EQUILIBRAGE ROUES
12/08/2024	53.517	RENAULT RETAIL GROUP	BOITIER SERVITUDE INTELLIGENT BSI RPLT
	0		DIVERS ELEC
	0		DIVERS ALIMENTATION
	0		DIVERS ECHAPPEMENT
	0		DIVERS ELEC
	0		RADIATEUR CHAUFFAGE HABITACLE RPLT
08/01/2024	42.035	RENAULT RETAIL GROUP	PILE DE CLE RPLT
	0		REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV
	0		PLAQUETTES AV RPLT
	0		BALAI ESSUIE GLACE AR
	0		RECYCLAGE
08/09/2023	34.577	CONTITRADE FRANCE	REPLACEMENT PNEUS ETE