



SKODA SUPERB: 1VPY545

Vinnumber:	TMBJN9NP5K7025096	Versionname:	
First Registrationdate:	23/01/2019	Fiscalpower:	
Expertise Mileage:	165933	Power Kw:	110
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front		
Fueltype:	Petrol		
Maintenance	OK		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Seats R heated	
Number keys remote	2	Seats electric F L	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Board Computer		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Steering wheel leather		Rear parking sensors	
Seats F heated		Roof bar alu	
Type of headlighting	Headlighting Xenon	Type of Tow bar	Tow bar collapsible
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of radio	Multimedia		
Type of GPS storage	HD		

Tyres

	215/55/17/98 W			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm
Tyre profile depth FL	6.0			
Tyre profile depth FR	6.0			
Tyre profile depth RL	6.0			
Tyre profile depth RR	6.0			
Tyre size FL	215/55 R 17 98 W			
Tyre size FR	215/55 R 17 98 W			
Tyre size RL	215/55 R 17 98 W			
Tyre size RR	215/55 R 17 98 W			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	261			
Tyre make FR	261			
Tyre make RL	261			
Tyre make RR	261			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Seat cover RL, Stain, Cleaning



Windscreen, Stone chip(s), Windscreen repair



Bumper F, Deformed / Strained, Replace and paint



Bonnet, Hail damage, Repair and paint (complete)



Wing FL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Acceptable



Wing RL, Dent(s), Paintless dent repair



Side window trim RL, Scratch(es), Replace



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Dent(s), Paintless dent repair



Step R, Scratch(es), Acceptable




Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Roof pillar R, Hail damage, Paintless dent repair (hail)



Alloy rim RR, Scratch(es), Acceptable



Door FR, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Roof, Hail damage, Paintless dent repair (hail)

