



FIAT DUCATO: GE-058-HP

Vinnumber:	ZFA25000002T68861	Versionname:	FIAT DUCATO 3.0 GNV 136 3.5 M H2 Pro Lounge VU [4P] bvm 6-136CH-8cv (fourgon tA IÃ@simple cabine)
First Registrationdate:	26/01/2022	Fiscalpower:	100
Expertise Mileage:	48394	Power Kw:	White
Bodytype:	Transporter	Body colour:	Opaque
Gearbox:	MAN 6 VIT	Paint type:	Black
Transmission:	Front	Interior colour:	Steel
Fueltype:	Diesel	Type of rims (mounted):	Black
Engine functioning:	Yes	Dashboard color:	
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	4	Tow bar	
Number keys remote	1	Central consol F	
Windows electric F		Rear parking sensors	
Cruise Control		Roof rack	
Steering wheel multifunctional		Sliding door right-side	
Steering wheel leather		Rear view camera	
Type of climate control	Manual climate control	Seat cover lining	Lining Other

Tyres

	215/70/15/109 S			
Summer tyres:	Fr.L.	Michelin: 30%	Fr.R.	Michelin: 10%
	Re.L.	Michelin: 20%	Re.R.	Michelin: 25%
Tyre profile depth FL				6.3
Tyre profile depth FR				7.5
Tyre profile depth RL				6.8
Tyre profile depth RR				6.5
Tyre size FL				215/70 R 15 109 S
Tyre size FR				215/70 R 15 109 S
Tyre size RL				215/70 R 15 109 S
Tyre size RR				215/70 R 15 109 S
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Jack

Yes

Outside rear-view mirror base L, Broken, Replace



Side repeater L, Broken, Replace



Side wall RL, Dent(s), Repair and paint (complete)



Number plate F, Deformed / Strained, Repair/replace (lump sum)



Outer sill R, Dent(s), Repair and paint (complete)



Sliding door R, Dent(s), Repair and paint (complete)



Outer door handle RR, Broken, Replace



Side repeater R, Broken, Replace



Outside rear-view mirror base R, Broken, Replace



Side panel moulding R, Broken, Replace



Boot moulding, Missing, Replace



Boot door panel RR, Dent(s), Repair and paint (complete)



Rear light L, Crack, Replace



Bumper R, Deformed / Strained, Replace



Rear light R, Crack, Replace



Historique Maintenance

Immatriculation: **GE-058-HP**

Date de 1ère immatriculation: **26/01/2022**

Modèle: **Fiat DUCATO 3.0 GNV 136 3.5 M H2 Pro Lounge VU [4P] bvm 6-136CH-8cv (fourgon tôlésimple
cabine)**

Date	Kilométrage	Fournisseur	Descriptif
18/07/2024	33.873	LE POIDS LOURD 92	DISQUES PLAQUETTES AV RPLT
	0		PLAQUETTES AR RPLT
	0		REVISION ET CLIM ET AIR ET BOUGIES
	0		LIQUIDE DE FREIN
	0		DIVERS
	0		DIAG
	0		LAMPE RPLT