

### Vehicle details

|                   |                    |              |  |                           |               |
|-------------------|--------------------|--------------|--|---------------------------|---------------|
| VIN               | WAUZZZFZ9 NP034666 | Brand        | AUDI   | Maintenance date          | -             |
| Licence Plate     |                    | Model        | Q4 e-tron 40 e-tron Launch edition Advanced 5d | Maintenance mileage       | -             |
| Registration date | 23/04/2022         | Year         | 2022   | Exterior Color            | Grey Metallic |
| Odometer          | 170 570 km         | Engine size  | -  | Interior Color            | Grey          |
| Fuel              | Electric           | Body Type    | -  | Next technical inspection | -             |
| Seats             | -                  | Transmission | Automatic                                      | CO2                       | -             |
| Doors             | 5                  | Gears        | -  |                           |               |

### Inspection Details


|                 |            |                 |  |
|-----------------|------------|-----------------|--|
| Inspection date | 29/06/2026 | Inspection loc. |  |
|-----------------|------------|-----------------|--|



| Generic equipment            | Removable element   | Technical Document        |
|------------------------------|---------------------|---------------------------|
| Automated air-conditioning ✓ | Rear parcel shelf ✓ | User manual ✓             |
| Cruise control ✓             | Vehicle charger ✓   | Spare key ✓               |
| GPS system ✓                 | Wireless charger ✗  | Remote key ✓              |
| Alloy wheel rims ✓           |                     | Sat Nav CD ROM Software ✓ |
| Automatic Gearbox ✓          |                     |                           |
| Heating seats ✓              |                     |                           |
| Metallic paint ✓             |                     |                           |
| Central locking ✓            |                     |                           |
| Electric windows ✓           |                     |                           |
| Side rails ✓                 |                     |                           |
| Park Distance Control ✓      |                     |                           |
| Audio System ✓               |                     |                           |
| Led lighting ✓               |                     |                           |

## Tyres

Pirelli 235/50/20 Summer 5.0 mm



Pirelli 235/50/20 Summer 5.0 mm



Pirelli 235/50/20 Summer 5.5 mm

Pirelli 235/50/20 Summer 5.5 mm

## Exterior

2



|             |                 |
|-------------|-----------------|
| Part        | Alloy wheel 20" |
| Position    | Front left      |
| Damages     | Scratched       |
| Severity    | -               |
| Repair mode | Lumpsum repair  |

3



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Front left         |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

4



|             |           |
|-------------|-----------|
| Part        | Door      |
| Position    | Back left |
| Damages     | Scratched |
| Severity    | -         |
| Repair mode | Repair    |

5



|             |           |
|-------------|-----------|
| Part        | Wing      |
| Position    | Back left |
| Damages     | Scratched |
| Severity    | -         |
| Repair mode | Repair    |

6



|             |           |
|-------------|-----------|
| Part        | Spoiler   |
| Position    | Back      |
| Damages     | Scratched |
| Severity    | -         |
| Repair mode | Repair    |

7



|             |           |
|-------------|-----------|
| Part        | Bumper    |
| Position    | Back      |
| Damages     | Scratched |
| Severity    | -         |
| Repair mode | Repair    |

8



|             |                 |
|-------------|-----------------|
| Part        | Alloy wheel 20" |
| Position    | Back right      |
| Damages     | Scratched       |
| Severity    | -               |
| Repair mode | Lumpsum repair  |

9



|             |                 |
|-------------|-----------------|
| Part        | Alloy wheel 20" |
| Position    | Front right     |
| Damages     | Scratched       |
| Severity    | -               |
| Repair mode | Lumpsum repair  |


10



|             |              |
|-------------|--------------|
| Part        | Bumper       |
| Position    | Front        |
| Damages     | Dent & Chips |
| Severity    | -            |
| Repair mode | Repair       |

## Others

1



|             |                  |
|-------------|------------------|
| Part        | Wireless charger |
| Position    | -                |
| Damages     | Missing          |
| Severity    | -                |
| Repair mode | For info         |