MACADAM








Skoda Enyaq (KKL): 2CPW427

Vinnumber:	**TMBJC7NY7PF009675**	Versionname:	**Enyaq iV 80 204pk/cv 5p**
First Registrationdate:	**12/10/2022**	Fiscalpower:	
Expertise Mileage:	**150172**	Power Kw:	**69**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Electric**		
Maintenance	**NOT OK**		
Maintenance	**sinds 3 dagen**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**235/55/19/101 T**			
	Fr.L.	**Pirelli: 5 mm**	Fr.R.	**Pirelli: 5 mm**
	Re.L.	**Pirelli: 4 mm**	Re.R.	**Pirelli: 4 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**235/55 R 19 101 T**
Tyre size FR	**235/55 R 19 101 T**
Tyre size RL	**255/50 R 19 103 T**
Tyre size RR	**255/50 R 19 103 T**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**264**
Tyre make FR	**264**
Tyre make RL	**264**
Tyre make RR	**264**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**0**		
Number of charging cables (rapid charge)	**1**		

Service, Maintenance, Check



Interior, Dirty, Cleaning



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Door RL, Dent(s), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Check



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Paintless dent repair



Outside rear-view mirror base R, Scratch(es), Acceptable




Onderhoudshistorie van: TMBJC7NY7PF009675

ALPHABET

Kenteken	2CPW427
Merk Model	Skoda Enyaq iV 80 204pk/cv 5p
Brandstofsoort	Elektrisch
Datum deel1	10/12/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
10/31/24	79,175	klein materiaal	
10/31/24	79,175	luchtfilter interieur	Vervangen
10/31/24	79,175	Onderhoudsbeurt (variabel interval)	Uitvoeren
10/31/24	79,175	remvloeistof	Vervangen
10/31/24	79,175	ruitenwisserrubber achter	Vervangen
10/31/24	79,175	ruitenwisserrubber vooraan	Vervangen