



Ford Mustang: L784RR

Vinnumber:	WF0TK1EM9MMA21582	Versionname:	Mustang Mach-E 190kW/ 75,7kWh RWD automaat
First Registrationdate:	20/07/2021	Fiscalpower:	
Expertise Mileage:	166407	Power Kw:	190
Bodytype:		Body colour	Shadow Black
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	633
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Lining leather
GPS		Rear parking sensors
Autom climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 60 / 18 / 100 / V / Aluminium	5,1 mm	Bridgestone	Summer
	Right	225 / 60 / 18 / 100 / V / Aluminium	5,1 mm	Bridgestone	Summer
Rear	Left	225 / 60 / 18 / 100 / V / Aluminium	5,1 mm	Continental	Summer
	Right	225 / 60 / 18 / 100 / V / Aluminium	5,4 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)





Bumper F, Scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Roof, Chemical polution, Repair and paint (complete)



Kenteken	L784RR
Merk Model	Ford Mustang Mach-E 198kW/ 75,7kWh RWD automaat
Brandstofsoort	Elektrisch
Datum deel1	20-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
27-06-25	125.725	APK
27-06-25	125.725	Ruitenwischerblad(en) voorzijde
24-05-24	86.264	Reparatie band(en)
13-09-23	60.949	Reparatie band(en)
10-01-23	37.306	Reparatie band(en)