



**FORD Kuga: 3387-MFW**

Vinnumber:	<b>WF0FXXWPMHNG14739</b>	Versionname:	<b>ST-Line X 2.5 Duratec FHEV 140kW 4x4 Aut todoterreno 140kW 5P automática</b>
First Registrationdate:	<b>29/03/2023</b>	Fiscalpower:	
Expertise Mileage:	<b>241665</b>	Power Kw:	
Bodytype:	<b>SUV</b>	Body colour:	<b>White</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:			
Fueltype:	<b>Hybrid</b>		
Engine functioning:	<b>Yes</b>		
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Radio
Number keys remote	<b>2</b>	Central consol F
GPS big screen color		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		Roof bar black
Steering wheel multifunction		
Steering wheel leather		
Radio multimedia		
Type of climate control	<b>Autom climate control</b>	

**Tyres**

<b>245/45/20/103 W</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 5 mm</b>	Fr.R.	<b>Goodyear: 5 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>245/45 R 20 103 W</b>
Tyre size FR				<b>245/45 R 20 103 W</b>
Tyre size RL				<b>245/45 R 20 103 W</b>
Tyre size RR				<b>245/45 R 20 103 W</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>259</b>
Tyre make FR				<b>259</b>
Tyre make RL				<b>259</b>
Tyre make RR				<b>259</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
<b>Boot lid covering R, Scratch(es), Replace</b>			



Interior, Dirty, Cleaning



User's manual, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Bumper F, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)




Door RR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering



Roof, Scratch(es), Repair and paint (complete)





## Datos del vehículo

---

Marca Matrícula  
Modelo VIN  
Versión

## Histórico

---

Fecha	Descripción	Kilómetros	Taller