



DS 7 CROSSBACK: GD-279-GY

Vinnumber:	VR1J45GFUMY542527	Versionname:	DS DS 7 CROSSBACK PureTech 180 Automatique
First Registrationdate:	1/12/2021	Fiscalpower:	LIGNE NOIRE VP [5P] bva 8-180CH-10cv (SUV)
Expertise Mileage:	111490	Power Kw:	132
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Sun Roof electric	
GPS big screen color		Panoramic roof	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Rear view camera	
Type of climate control	Autom climate control	Seat cover lining	Lining Leather

Tyres

235/50/19/103 V				
Winter tyres:	Fr.L.	Kleber: 80%	Fr.R.	Kleber: 75%
	Re.L.	Kleber: 80%	Re.R.	Kleber: 90%
Tyre profile depth FL				3.0
Tyre profile depth FR				3.2
Tyre profile depth RL				2.7
Tyre profile depth RR				2.0
Tyre size FL				235/50 R 19 103 V
Tyre size FR				235/50 R 19 103 V
Tyre size RL				235/50 R 19 103 V
Tyre size RR				235/50 R 19 103 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2479
Tyre make FR				2479
Tyre make RL				2479
Tyre make RR				2479

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Interior, Dirty, Chemical cleaning



Roof liner, Unclasp(ed), Dismount/Mount



Interior trim, Unclasp(ed), Dismount/Mount



Interior trim, Unclasp(ed), Dismount/Mount



Malfunction indicator, Blinking, Check



Seat cover FL, Tear, Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Acceptable



Tyres, Out of tolerance, Replace





Historique Maintenance

Immatriculation: **GD-279-GY**

Date de 1ère immatriculation: **01/12/2021**

Modèle: **DS 7 CROSSBACK PureTech 180 Automatique LIGNE NOIRE VP [5P] bva 8-180CH-10cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
14/08/2025	90.885	MIDI AUTO 19	ESSAI
	0		DIAG
	0		TELECHARGEMENT CALCULATEUR
02/06/2025	84.816	NOMBLOT VILLEFRANCHE	DIVERS ECHAPPEMENT
29/04/2025	82.438	NOMBLOT VILLEFRANCHE	REVISION
	0		FILTRE CLIM RPLT
04/04/2025	82.438	NOMBLOT VILLEFRANCHE	COURROIE ACCESSOIRES RPLT
17/12/2024	79.999	NOMBLOT AUTOMOBILES	DIVERS SUSPENSION
	0		CREMAILLERE DE DIRECTION RPLT
	0		PLAQUETTES AV RPLT
22/01/2024	60.000	NOMBLOT AUTOMOBILES	LIQUIDE DE FREIN
	0		FILTRE CLIM RPLT
	0		DISQUES PLAQUETTES AR RPLT
	0		BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		REVISION
	0		BOITIER D ALLUMAGE RPLT
	0		FILTRE A AIR RPLT
23/01/2023	27.996	NOMBLOT AUTOMOBILES	REVISION
	0		BALAI ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR