

2-FAJ-891

2-FAJ-891 · Move! 1.0 TSI 110cv DSG unicolor · 30 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FAJ-891	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJXRR087078
Model	Arona	Cylinder Capacity	999 ^{cm³}
Model Versions	Move! 1.0 TSI 110cv DSG unicolor	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	06-03-2024
Color	Blue	Odometer	92.889 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	81	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	1 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	1 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part
Reardoor - Left

Damage Type
Stonechipping

Repair Type
Touch-up / Polish

Acceptable
No



Damage Part
Frontdoor - Left

Damage Type
small dents / small scratches

Repair Type
Restyle / Touch-up

Acceptable
No



Damage Part
Windscreen - Front

Damage Type
Chipped

Repair Type
Window Repair

Acceptable
No



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Stonechipping

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Front

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Right

Small scratch(es)

Polish

No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Right	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Right	Dent(s) & Scratch(es)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Damaged	Touch-up / Polish	No





Damage Part

Damage Type

Repair Type

Acceptable

Roof

Small scratch(es)

Polish

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Rear door - Right

Scratch(es)

Bekleding

Cloth Repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Rear seat

Stains & dirt

Cleaning

No