



PEUGEOT 308 3

-	
VIN	VR3F3DGXTPY651022
Première immatriculation	24/11/2023

DÉTAILS DE L'INSPECTION

Date de l'inspection

INFORMATIONS SUR LE VÉHICULE

VIN	VR3F3DGXTPY651022	Transmission	Avant
Type de carrosserie	Berline	Nbre sièges	5
Nbre portes	5	Nombre appuis-têtes	5
Première immatriculation	24/11/2023	Couleur intérieur	Noir
Type de carburant	Hybride rechargeable	Couleur carrosserie	Noir
Marque	PEUGEOT	Catégorie	Vehicule particulier
Modèle	308 3	Couleur tableau de bord	Noir
Boîte de vitesses	Automatique		

DOCUMENTS ET CLÉS

Carnet d'entretien	Non	Manuel d'utilisation	Non
Nbre clés total	2	Certificat immatriculation (original)	Original
Nbre clés télécommandes	2	Certificat immatriculation (original)	Oui

OPTIONS

Camera de recul	Oui	Nature de peinture	Metallisé
-----------------	-----	--------------------	-----------

DAMAGES

Exterior



1 | Tyre FL

Damage type	Out of tolerance
Repair mode	Replace



2 | Alloy rim FL bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



3 | Alloy rim RR bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



4 | Tyre FR

Damage type	Out of tolerance
Repair mode	Replace



5 | Alloy rim FR bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



6 | Wing FL

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



7 | Bumper F

Damage type	Scratch(es)
Repair mode	Repair and paint (complete)



8 | Bonnet

Damage type	Stone chip(s)
Repair mode	Paint



9 | Outer sill R

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



10 | Wing FR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)

Commercial photos

