



## Volvo XC 40

Vinnumber:	<b>YV1XZ15VDM2605794</b>	Versionname:	
First Registrationdate:	<b>19/05/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>133376</b>	Power Kw:	
Bodytype:		Body colour:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>2733</b>
Fueltype:	<b>Petrol</b>		
Maintenance:	<b>OK</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

## Options

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	<b>Tow bar fixed</b>
Radio multimedia:			
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		
Type of GPS storage:	<b>HD</b>		

## Limited Technical Inspection

## Tyres

235/55/18/104 V				
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 3 mm</b>	Re.R.	<b>Michelin: 3 mm</b>
Tyre profile depth FL				<b>3.0</b>
Tyre profile depth FR				<b>3.0</b>
Tyre profile depth RL				<b>3.0</b>
Tyre profile depth RR				<b>3.0</b>
Tyre size FL				<b>235/55 R 18 104 V</b>
Tyre size FR				<b>235/55 R 18 104 V</b>
Tyre size RL				<b>235/55 R 18 104 V</b>
Tyre size RR				<b>235/55 R 18 104 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>261</b>
Tyre make FR				<b>261</b>
Tyre make RL				<b>261</b>
Tyre make RR				<b>261</b>

## Assistance equipment

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT:	<b>367,64</b>
Engine insulation, Damaged, Replace:	<b>0,00</b>



Bumper F, Scratch(es), Acceptable 0,00



Alloy rim FL, Scratch(es), Acceptable 0,00



Wing RL, Dent(s), Acceptable 0,00



Alloy rim RL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Boot lid covering R, Scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Repair and paint (complete) 133,03



Wing trim RR, Scratch(es), Replace 101,58



Wing RR, Scratch(es), Acceptable 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete)

133,03

