



### Skoda Octavia

Vinnumber:	<b>TMBAW7NX3NY072286</b>	Versionname:	
First Registrationdate:	<b>8/07/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>192298</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3120</b>
Fueltype:	<b>Hybrid Petrol</b>		
Maintenance:	<b>NOT OK</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

### Options

Number of keys total:	<b>2</b>	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	<b>No Tow bar</b>
Radio multimedia:			
Type of headlighting:	<b>Headlighting LED</b>		
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		

### Limited Technical Inspection

### Tyres

205/55/17/92 H				
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>205/55 R 17 92 H</b>
Tyre size FR				<b>205/55 R 17 92 H</b>
Tyre size RL				<b>205/55 R 17 92 H</b>
Tyre size RR				<b>205/55 R 17 92 H</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>256</b>
Tyre make FR				<b>256</b>
Tyre make RL				<b>256</b>
Tyre make RR				<b>256</b>

### Assistance equipment

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>1</b>		
Number of charging cables (rapid charge):	<b>1</b>		

Total cost ex VAT:	<b>124,63</b>
Seat cover FR, Stain, Cleaning:	<b>29,16</b>



Service, Maintenance, Check 0,00



Bonnet, Dent(s), Repair and paint (complete) 0,00



repaired, Acceptable 0,00



and repair, Check 0,00



Tailgate / Boot, Scratch(es), Acceptable 0,00



Step R, Scratch(es), Acceptable 0,00



Wing RR, Scratch(es), Acceptable 0,00



Wing RR, Dent(s), Paintless dent repair 95,47

