



Peugeot 308:

Vinnumber:	VR3F4DGXTNY559194	Versionname:	
First Registrationdate:	8/07/2022	Fiscalpower:	
Expertise Mileage:	135160	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3616
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

225/45/17/91 Y				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Goodyear: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				225/45 R 17 91 Y
Tyre size FR				225/45 R 17 91 Y
Tyre size RL				225/45 R 17 91 Y
Tyre size RR				225/45 R 17 91 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				259

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	1		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	964,60
Interior, Damaged, Acceptable	0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Step L, Dent(s), Acceptable 0,00



Wing RL, Dent(s), Acceptable 0,00



Boot lid covering R, Scratch(es), Acceptable 0,00



Bumper moulding R, Scratch(es), Acceptable 0,00



Charging cable (fast), Missing, Replace 256,50



Bumper R, Scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21





Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21



Wing RR, Dent(s), Acceptable 0,00



Door RR, Dent(s), Acceptable 0,00



Roof, Dent(s), Paintless dent repair 95,47



Bodywork, Not original part, Remove lettering 0,00

