



Volvo XC40: L015RL

Vinnumber:	YV1XZBBVFM2592264	Versionname:	XC40 T5 Plug-In Hybrid 193kW R-Design geartronic
First Registrationdate:	16/07/2021	Fiscalpower:	
Expertise Mileage:	137242	Power Kw:	132
Bodytype:		Body colour	Onyx Black metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Hybrid Petrol	Parking lot	569
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Lining semi-leather
GPS		Lining Alcantara
Autom climate control		Rear parking sensors
Radio multimedia		Rear view camera

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 50 / 19 / 103 / V / Aluminium	5,2 mm	Continental	Summer
	Right	235 / 50 / 19 / 103 / V / Aluminium	5,5 mm	Continental	Summer
Rear	Left	235 / 50 / 19 / 103 / V / Aluminium	3,0 mm	Continental	Summer
	Right	235 / 50 / 19 / 103 / V / Aluminium	2,2 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------

Service, Maintenance, Execute



Door FL, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Bad repair, Repair and paint (complete)



Door FR, Bad repair, Repair and paint (complete)



Kenteken	L015RL
Merk Model	Volvo XC40 T5 Plug-In Hybrid 193kW R-Design geartronic
Brandstofsoort	Benzine
Datum deel1	16-07-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
03-09-25	115.223	Vervanging band
02-07-25	110.068	APK
02-07-25	110.068	Bougie
02-07-25	110.068	Luchtfilter
02-07-25	110.068	Onderhoudsbeurt
02-07-25	110.068	Volvo Check aandrijving
02-07-25	110.068	Volvo Check slijtagedelen
13-05-24	80.311	Elektrische achterklep
13-05-24	80.311	Onderhoudsbeurt
13-05-24	80.311	Volvo Check slijtagedelen
02-05-23	53.947	Bougie
02-05-23	53.947	Luchtfilter
02-05-23	53.947	Onderhoudsbeurt
02-05-23	53.947	Ruitenwisserblad(en) voorzijde
02-05-23	53.947	Volvo Check aandrijving
02-05-23	53.947	Volvo Check slijtagedelen
21-06-22	24.769	Onderhoudsbeurt
21-06-22	24.769	Volvo Check slijtagedelen