



Mercedes GLA-Klasse (UKL): 2C6X290

Vinnumber:	W1N2477861J389824	Versionname:	GLA250e Business Solution 1.3i 218pk/cv 5p 8G-DCT
First Registrationdate:	9/06/2022	Fiscalpower:	
Expertise Mileage:	99726	Power Kw:	118
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

235/55/18/100 V				
Summer tyres:	Fr.L.	Hankook: 4 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Hankook: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				4.0
Tyre size FL				235/55 R 18 100 V
Tyre size FR				235/55 R 18 100 V
Tyre size RL				235/55 R 18 100 V
Tyre size RR				235/55 R 18 100 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				255
Tyre make RL				255
Tyre make RR				260

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Backrest cover FL, Scratch(es), Acceptable



Windscreen, Bad repair, Replace



Central pillar L, Dent(s) and scratch(es), Spot repair



Alloy rim RL polished, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Tailgate / Boot, Dent(s) and scratch(es), Acceptable



Bumper R, Scratch(es), Polish



Wing RR, Dent(s), Acceptable



Kenteken	2CCX290
Merk Model	Mercedes GLA250e Business Solution 1.3i 218pk/cv 5p 8G-DCT
Brandstofsoort	Benzine
Datum deel1	6/9/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/23/26	98,768	dakgel. smeren	Uitvoeren
6/23/26	98,768	klein materiaal	
6/23/26	98,768	mercedes assyst b	Uitvoeren
6/23/26	98,768	trekhaak	Controleren
6/27/25	74,079	bougie	Vervangen
6/27/25	74,079	klein materiaal	
6/27/25	74,079	luchtfilter	Vervangen
6/27/25	74,079	mercedes assyst a	Uitvoeren
6/27/25	74,079	remvloeistof	Vervangen
6/25/24	47,306	dakgel. smeren	Uitvoeren
6/25/24	47,306	klein materiaal	Uitvoeren
6/25/24	47,306	mercedes assyst b	Uitvoeren
6/25/24	47,306	ruitenswisserrubber achter	Vervangen
6/25/24	47,306	ruitenswisserrubber vooraan	Vervangen
6/25/24	47,306	trekhaak	Controleren
7/7/23	24,262	klein materiaal	Uitvoeren
7/7/23	24,262	mercedes assyst a	Uitvoeren
12/9/22	11,527	ruitenswisserrubber vooraan	Vervangen