MACADAM









VOLKSWAGEN POLO: GJ-318-SB

Vinnumber:	**WVWZZZAWZPY002948**	Versionname:	**VOLKSWAGEN POLO 1.0 TSI 110 DSG7 Life Business VP [5P] bva 7-110CH-6cv (bi-corps)**
First Registrationdate:	**28/09/2022**	Fiscalpower:	
Expertise Mileage:	**47248**	Power Kw:	**81**
Bodytype:	**Berline**	Body colour	**Blue**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Petrol**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	**Lining Other**
Steering wheel leather			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**185/65/15/88 H**			
	Fr.L.	**Kumho: 35%**	Fr.R.	**Kumho: 50%**
	Re.L.	**Kumho: 55%**	Re.R.	**Kumho: 60%**

Tyre profile depth FL	**5.8**
Tyre profile depth FR	**4.9**
Tyre profile depth RL	**4.7**
Tyre profile depth RR	**4.2**
Tyre size FL	**185/65 R 15 88 H**
Tyre size FR	**185/65 R 15 88 H**
Tyre size RL	**185/65 R 15 88 H**
Tyre size RR	**185/65 R 15 88 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**2482**
Tyre make FR	**2482**
Tyre make RL	**2482**
Tyre make RR	**2482**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Interior, Stain, Cleaning







Door FL, Scratch(es), Acceptable




Door RL, Dent(s), Repair and paint (complete)




Bonnet, Dent(s), Acceptable




Roof, Hail damage, Repair and paint (complete)




ALPHABET

Historique Maintenance

Immatriculation: **GJ-318-SB** Date de 1ère immatriculation: **28/09/2022**

Modèle: **Volkswagen POLO 1.0 TSI 110 DSG7 Life Business VP [5P] bva 7-110CH-6cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
22/10/2024	21.113	GVA BYMYCAR LYON	REVISION
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN