



RENAULT MASTER: GJ-142-RB

Vinnumber:	VF1MA000169472726	Versionname:	RENAULT MASTER FG Tr GCF F3500 L2H2 Blue dCi 135 VU [4P] bvm 6-135CH-8cv (fourgon tA 1A@simple cabine)
First Registrationdate:	27/09/2022	Fiscalpower:	
Expertise Mileage:	184745	Power Kw:	99
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	2	Radio	
Number keys remote	2	Rear parking sensors	
GPS big screen color		Sliding door right-side	
Windows electric F		Rear view camera	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Type of climate control	Manual climate control		

Tyres

	225/65/16/112 R			
Summer tyres:	Fr.L.	Pirelli: 0%	Fr.R.	Pirelli: 0%
	Re.L.	Michelin: 0%	Re.R.	Michelin: 0%
Tyre profile depth FL				8.5
Tyre profile depth FR				8.5
Tyre profile depth RL				8.7
Tyre profile depth RR				8.4
Tyre size FL				225/65 R 16 112 R
Tyre size FR				225/65 R 16 112 R
Tyre size RL				225/65 R 16 112 R
Tyre size RR				225/65 R 16 112 R
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Interior, Dirty, Cleaning			



Seat cover FL, Tear, Replace



Door seal FL, Tear, Replace



Inner door sill FL, Scratch(es), Paint



Outer sill L, Scratch(es), Paint



Bumper F, Scratch(es), Acceptable



Bumper grille, Unclassped, Dismount/Mount



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RR, Scratch(es), Paint



Rubber seal for boot lid, Tear, Replace



Rear bulkhead lining, Broken, Replace



Boot door lining L, Broken, Replace



Boot door panel RR, Dent(s), Repair and paint (complete)



Bodywork, Glue residues, Remove lettering



Historique Maintenance

Immatriculation: **GJ-142-RB** Date de 1ère immatriculation: **27/09/2022**

Modèle: **Renault MASTER FG Tr GCF F3500 L2H2 Blue dCi 135 VU [4P] bvm 6-135CH-8cv (fourgon tôle simple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
27/07/2026	184.745	J L CARS	DIVERS
			Petite Fourniture moteur
			Alimentation
			Main D'œuvre
			Essai routier
			Injecteur de carburant (Remplacement)
			DIVERS
			INJECTEUR RPLT
			DIAG
			ESSAI
14/04/2026	176.481	GARAGE BULTEZ MAING	RADIATEUR REFROIDISSEMENT MOTEUR RPLT
			LIQUIDE DE REFROIDISSEMENT RPLT
			RADIATEUR REFROIDISSEMENT MOTEUR RPLT
19/12/2025	162.052	SARL BULTEZ	REVISION ET CLIM
			REVISION
			KIT ACCESSOIRES RPLT
			ECLAIRAGE DE PLAQUE RPLT
			LAMPE RPLT
			DIVERS ECHAPPEMENT
13/10/2025	152.763	SARL BULTEZ	ECLAIRAGE DE PLAQUE RPLT
			LAMPE RPLT
			PLAQUETTES AV RPLT
			PLAQUETTES AR RPLT
12/02/2025	121.870	SARL BULTEZ	BALAIS ESSUIE GLACE AV
			ADBLUE
			REVISION
19/12/2024	113.200	SARL BULTEZ	LAMPE CODE AVD RPLT
21/10/2024	103.109	SARL BULTEZ	PLAQUETTES AR RPLT
			ETRIERS AV RPLT
			DISQUES PLAQUETTES AV RPLT
26/04/2024	78.527	SARL BULTEZ	LIQUIDE DE FREIN
			REVISION

Historique Maintenance

Immatriculation: **GJ-142-RB**

Date de 1ère immatriculation: **27/09/2022**

Modèle: **Renault MASTER FG Tr GCF F3500 L2H2 Blue dCi 135 VU [4P] bvm 6-135CH-8cv (fourgon tôle simple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
			REVISION ET CLIM
			BALAIS ESSUIE GLACE AV
31/01/2024	63.992	SARL BULTEZ	DISQUES PLAQUETTES AR RPLT
			PLAQUETTES AV RPLT
07/09/2023	39.981	SARL BULTEZ	REVISION ET CLIM