



Kia Sorento (KKL): 2BFX484

Vinnumber:	KNARM81HDN5071051	Versionname:	Sorento Sense 1.6TGi PHEV 265pk/cv 5p 4WD AT6
First Registrationdate:	9/11/2021	Fiscalpower:	
Expertise Mileage:	114353	Power Kw:	132
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Maintenance book present		
Type of GPS storage	HD		

Tyres

235/55/19/105 W				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 2 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				4.0
Tyre profile depth RL				3.0
Tyre profile depth RR				2.0
Tyre size FL				235/55 R 19 105 W
Tyre size FR				235/55 R 19 105 W
Tyre size RL				235/55 R 19 105 W
Tyre size RR				235/55 R 19 105 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Engine insulation, Damaged, Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Door FL, Dent(s), Acceptable



Step L, Dent(s) and scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Bumper moulding R, Scratch(es), Acceptable




Alloy rim RR polished, Scratch(es), Acceptable




Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door trim RR, Scratch(es), Smart repair



Door FR, Dent(s), Acceptable



Outside rear-view mirror R, complete, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Tyre FR, Tear, Acceptable



Kenteken	2BFX484
Merk Model	Kia Sorento Sense 1.6TGi PHEV 265pk/cv 5p 4WD AT6
Brandstofsoort	Benzine
Datum deel1	11/9/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/7/26	108,821	oliezeef	Vervangen
4/7/26	108,821	ruitenswisserrubber vooraan	Vervangen
9/16/25	94,232	90000 km	Uitvoeren
9/16/25	94,232	luchtfILTER interieur	Vervangen
9/16/25	94,232	oliezeef	Vervangen
12/12/24	80,078	75000 km	Uitvoeren
12/12/24	80,078	oliezeef	Vervangen
3/25/24	64,017	60000 km	Uitvoeren
3/25/24	64,017	luchtfILTER	Vervangen
3/25/24	64,017	luchtfILTER interieur	Vervangen
3/25/24	64,017	oliezeef	Vervangen
9/11/23	48,021	oliezeef	Vervangen
9/11/23	48,021	onderhoud 3e jaar	Uitvoeren
1/17/23	30,775	30000 km	Uitvoeren
1/17/23	30,775	ruitenswisserrubber vooraan	Vervangen
6/10/22	15,156	oliezeef	Vervangen
6/10/22	15,156	onderhoud 12 maand	Uitvoeren