

INSPECTION REPORT


End of contract

GENERAL INFO

File	316881
License plate	2APD302
Vehicle identification number	WAUZZZF45MA060770
Dossier	2020323017
Make	Audi A4 Av.30 TDi Advan.Bus.Ed
Mileage	103211
First registration	01/06/2021
client availability date	07/07/2026
inspectionDate	10/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
100	Door Rear Left // Smart Repair Small	N
112	Wing Rear Left // Smart Repair Large	N
86	Door Front Left // Polish	Y
183	Wing Rear Right // Painting	Y
331	Wheel Alloy Rear Right // Repair	N
417	Seat Front Left / Headrest / Replace	Y

Damage Pictures



Seat Front Left / Headrest / Replace-worn



Door Front Left // Polish-scratch



Wing Rear Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Rear Left // Smart Repair Small-scratch



Wing Rear Left // Smart Repair Large-scratch + dent