



VOLKSWAGEN PASSAT VARIANT:

Vinnumber:	WVWZZZ3CZLE099412	Versionname:	1.4 TSI DSG6 GTE Business
First Registrationdate:	4/05/2020	Fiscalpower:	
Expertise Mileage:	156602	Power Kw:	160
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1322
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar collapsible
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

215/55/17/92 H				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 17 92 H
Tyre size FR				215/55 R 17 92 H
Tyre size RL				215/55 R 17 92 H
Tyre size RR				215/55 R 17 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Total cost ex VAT	429,61
Bumper F, Scratch(es), Repair and paint (complete)	296,58



Bonnet, Scratch(es), Acceptable 0,00



Alloy rim RL, Scratch(es), Acceptable 0,00



Door FL, Scratch(es), Acceptable 0,00



Wing FL, Scratch(es), Acceptable 0,00



Bumper R, Dent(s) and scratch(es), Replace and paint 0,00



Rear window, Scratch(es), Replace 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Roof, Dent(s) and scratch(es), Acceptable 0,00

