



Seat Tarraco (UKL): 2AHB808

Vinnnumber:	VSSZZZKNZMW501774	Versionname:	Tarraco Xcellence 1.4TSi e-Hybrid 245pk/cv 5p DSG6
First Registrationdate:	1/04/2021	Fiscalpower:	
Expertise Mileage:	54719	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Hybrid Petrol		
Maintenance	OK		
Maintenance	plus 13500 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	235/50/19/99 V			
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 3 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				3.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/50 R 19 99 V
Tyre size FR				235/50 R 19 99 V
Tyre size RL				235/50 R 19 99 V
Tyre size RR				235/50 R 19 99 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	2		
Number of charging cables (rapid charge)	1		

Bumper F, Dent(s) and scratch(es), Repair and paint (complete)





Bumper spoiler F, Scratch(es), Replace



Bonnet, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Acceptable



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Bumper trim R, Dent(s) and scratch(es), Smart repair



Bumper moulding R, Dent(s) and scratch(es), Replace



Wing RR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable





Door FR, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Kenteken	2AHB808
Merk Model	Seat Tarraco Xcellence 1.4TSi e-Hybrid 245pk/cv 5p DSG6
Brandstofsoort	Benzine
Datum deel1	4/1/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/5/26	53,215	klein materiaal	
5/5/26	53,215	remvloeistof	Vervangen
5/5/26	53,215	ruitenwisserrubber achter	Vervangen
5/5/26	53,215	ruitenwisserrubber vooraan	Vervangen
5/5/26	53,215	ruitenwisservloeistof	Bijvullen/-laden
5/5/26	53,215	Tussentijds onderhoud (vast interval)	Uitvoeren
5/5/26	53,215	versnellingsbakolie	Vervangen
5/26/25	44,561	0139-Aanvulling op onderhoudsbeurt	Uitvoeren
5/26/25	44,561	bougie	Vervangen
5/26/25	44,561	Inspectie met olie vervanging (vast interval)	Uitvoeren
5/26/25	44,561	klein materiaal	
5/26/25	44,561	luchtfilter interieur	Vervangen
5/26/25	44,561	ruitenwisservloeistof	Bijvullen/-laden
5/26/25	44,561	waterafvoer open dak	Reinigen
4/19/24	34,503	klein materiaal	Uitvoeren
4/19/24	34,503	koelwatervloeistof	Bijvullen/-laden
4/19/24	34,503	remvloeistof	Vervangen
4/19/24	34,503	ruitenwisservloeistof	Bijvullen/-laden
4/19/24	34,503	Tussentijds onderhoud (vast interval)	Uitvoeren
4/19/24	34,503	vergrendelingsmotor (deur, koffer, tank)	Vervangen
4/11/23	23,279	Inspectie met olie vervanging (vast interval)	Uitvoeren
4/11/23	23,279	klein materiaal	Uitvoeren
4/11/23	23,279	koelwatervloeistof	Bijvullen/-laden
4/11/23	23,279	luchtfilter interieur	Vervangen
4/11/23	23,279	ruitenwisserrubber achter	Vervangen
4/11/23	23,279	ruitenwisserrubber vooraan	Vervangen
4/11/23	23,279	ruitenwisservloeistof	Bijvullen/-laden
4/11/23	23,279	waterafvoer open dak	Reinigen
4/5/22	10,432	klein materiaal	Uitvoeren
4/5/22	10,432	ruitenwisserrubber achter	Vervangen
4/5/22	10,432	ruitenwisserrubber vooraan	Vervangen
4/5/22	10,432	ruitenwisservloeistof	Bijvullen/-laden
4/5/22	10,432	Tussentijdse onderhoudsbeurt (variabel interval)	Uitvoeren