



MERCEDES C BREAK: [REDACTED]			
Vinnumber:	W1K2052531G045036	Versionname:	C 300 e Business Solution Auto
First Registrationdate:	8/09/2020	Fiscalpower:	
Expertise Mileage:	205337	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3312
Fueltype:	Hybrid Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
Summer tyres:	225/40/18/97 V		
	Fr.L.	Continental: 4 mm	Fr.R. Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R. Continental: 4 mm
Tyre profile depth FL			4.0
Tyre profile depth FR			4.0
Tyre profile depth RL			4.0
Tyre profile depth RR			4.0
Tyre size FL			225/40 R 18 97 V
Tyre size FR			225/40 R 18 97 V
Tyre size RL			245/40 R 18 97 V
Tyre size RR			245/40 R 18 97 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256
Assistance equipment			
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		
Total cost ex VAT			2084,85
Interior, Damaged, Acceptable			0,00



Seat cover FL, Hole, Replace	427,32
------------------------------	--------



Alloy rim FL polished, Scratch(es), Repair/replace (lump sum)	0,00
---	------



Alloy rim RL polished, Scratch(es), Repair and paint (complete)	204,21
---	--------



Wing RL, Dent(s) and scratch(es), Acceptable	0,00
--	------



Charging cable (normal), Missing, Check	0,00
---	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Rear window, Scratch(es), Replace	574,85
-----------------------------------	--------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	204,21
---	--------





Tyre FR, Tear, Acceptable	0,00
---------------------------	------



Alloy rim RR polished, Scratch(es), Acceptable	0,00
--	------



Roof, Chemical polution, Repair and paint (complete)	674,26
--	--------

