MACADAM










CITRO?N BERLINGO: FN-570-BC

Vinnumber:	**VR7EFYHWCKJ812590**	Versionname:	**CITRO?N BERLINGO Taille M 1000kg BlueHDi 75 BVM Club VU [4P] bvm 5-75CH-5cv (fourgonnettesimple cabine)**
First Registrationdate:	**15/01/2020**	Fiscalpower:	
Expertise Mileage:	**137900**	Power Kw:	**55**
Bodytype:	**Berline**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Grey**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**2**	Tow bar	
Number keys remote	**1**	Radio	
Windows electric F		Rear parking sensors	
Cruise Control		Sliding door right-side	
Type of climate control	**Manual climate control**	Seat cover lining	**Lining Other**

Tyres

Summer tyres:	**215/65/16/102 H**			
	Fr.L.	**Other: 50%**	Fr.R.	**Other: 50%**
	Re.L.	**Other: 50%**	Re.R.	**Other: 50%**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.8**
Tyre size FL	**215/65 R 16 102 H**
Tyre size FR	**215/65 R 16 102 H**
Tyre size RL	**215/65 R 16 102 H**
Tyre size RR	**215/65 R 16 102 H**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**263**
Tyre make FR	**263**
Tyre make RL	**263**
Tyre make RR	**263**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Inner door sill RR, Scratch(es), Paint





Inner door sill FL, Scratch(es), Paint





Seat cover FR, Worn, Acceptable






Seat cover FL, Worn, Acceptable




Outside rear-view mirror housing L, Scratch(es), Replace




Door trim FL, Broken, Replace






Bumper F, Scratch(es), Repair and paint (complete)







Bumper moulding FL, Scratch(es), Replace





Door FR, Dent(s) and scratch(es), Repair and paint (complete)







Outside rear-view mirror housing R, Scratch(es), Replace




Rubber seal for boot lid, Tear, Replace





Rear floor trunk, Rust, Paint




Rear bulkhead lining, Scratch(es), Acceptable





Bumper R, Scratch(es), Repair and paint (complete)






Boot door panel RL, Dent(s) and scratch(es), Acceptable






Bodywork, Not original part, Acceptable










ALPHABET

Historique Maintenance

Immatriculation: **FN-570-BC** Date de 1ère immatriculation: **15/01/2020**

Modèle: **Citroen BERLINGO Taille M 1000kg BlueHDi 75 BVM Club VU [4P] bvm 5-75CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
26/06/2026	133.458	TOUCHE AUTOMOBILES SARL	CONTROLE PH LIQUIDE REFROIDISSEMENT
			COURROIE ACCESSOIRES RPLT
			PLAQUETTES AR RPLT
			REVISION ET CLIM ET AIR ET CARBURANT
			LIQUIDE DE FREIN
			DISQUES PLAQUETTES AV RPLT
16/01/2026	123.527	CTVL ROCHELAIS	ANTIPOLLUTION
26/05/2025	109.461	TOUCHE AUTOMOBILES SARL	FAP RPLT
			DIAG
07/02/2025	103.565	CTVL ROCHELAIS	CONTRE VISITE POLLUTION
04/02/2025	103.447	TOUCHE AUTOMOBILES SARL	SONDE LAMBDA RPLT
			ADBLUE
			ESSAI
			INJECTEUR ADBLUE RPLT
26/02/2025	103.377	SUGAR	AVOIR
21/02/2025	103.377	CTVL ROCHELAIS	ANTIPOLLUTION
31/01/2025	103.377	SUGAR	ANTIPOLLUTION
16/01/2025	102.272	CLARIS AUTOMOBILES	BALAIS ESSUIE GLACE AV
			REVISION
			FILTRE A AIR RPLT
			FILTRE CLIM RPLT
			REVISION
08/11/2024	79.899	CTVL ROCHELAIS	DIVERS ECHAPPEMENT
02/02/2024	79.899	CONTROLE TECHNIQUE DU VAL DU LOIR	CONTROLE TECHNIQUE
26/01/2024	79.178	CLARIS AUTOMOBILES	TELECHARGEMENT CALCULATEUR
31/01/2023	59.925	CLARIS AUTOMOBILES	FILTRE CLIM RPLT
			DISQUES PLAQUETTES AV RPLT
			BALAIS ESSUIE GLACE AV
			REVISION
			FILTRE A AIR RPLT
			LIQUIDE DE FREIN
			REVISION

Historique Maintenance

Immatriculation: **FN-570-BC** Date de 1ère immatriculation: **15/01/2020**

Modèle: **Citroen BERLINGO Taille M 1000kg BlueHDi 75 BVM Club VU [4P] bvm 5-75CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
04/05/2021	17.893	CLARIS AUTOMOBILES	BALAIS ESSUIE GLACE AV
			REVISION