SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Bas Vaasen

2-GDK-513

2-GDK-513 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / · 4 November 2026 · Zaventem Brussel

Specifications

License Plate Number	2-GDK-513
Manufacturer	TOYOTA
Model	Corolla Cross
Model Versions	Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT /
Body Type	5 door hatchback
Color	Black
Paint Type	Metallic
Production Year	2024
KW	103
Fuel Type	Hybrid Gasoline

VIN	JTNADADB10J024291
Cylinder Capacity	1.798 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	05-11-2024
First Registration	05-11-2024
Odometer	53.854 Km
Numer Of Keys	2
Interior	Black – Cloth
Number Headrests	5

Images
































Accessories

ABS	Electric rear windows
Airbags	Electric windows front
Alloy wheels	Electrically adjustable exterior mirrors
ASR	Leather steering wheel
Audio System	Navigation system
Automatic air conditioning	Parking sensors
Bluetooth car kit	Rear view camera
Central door locking	Roller cover / parcel shelf
Centre armrest	Steering wheel multifunction
Cruise control	

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown
Dog in the car			

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 mm	UniRoyal	215 mm	60 mm	17 inch	All Season
Rear Left	5 mm	UniRoyal	215 mm	60 mm	17 inch	All Season
Front Right	5 mm	UniRoyal	215 mm	60 mm	17 inch	All Season
Rear Right	5 mm	UniRoyal	215 mm	60 mm	17 inch	All Season
Spare Tire Type	Homecomer					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	small dents / small scratches	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Left Front	Scratch(es)	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Door-edge chipped	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Small scratch(es)	Acceptable	Yes










Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Stains & dirt	tevens hondenharen	Cleaning	No